

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 12 and 13

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 1994)

Set ¼ sec. post, from which
A Fir 50" dia., bears S.32°W., 33 lks. dist.
a Fir 15" dia., bears N.40°W., (omitted)

GLO survey by Charles A. Slang, Deputy Surveyor, under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 2103 and 2104)

The old ¼ sec. cor. which is a post in good condition but marks on witness trees are about all destroyed.
A Fir 50" dia., bears N.86°W., 48 lks. dist. mkd. ¼ S12 BT.
A Fir 50" dia., bears S.60°W., 109 lks. dist. mkd. ¼ S13 BT.

Survey by Clifford A. Stephens - For: J. Lightfoot - May/June 1965 - C.S. File 51/321 and M 22-72

Found 3" x 4½ ft. Alder post for the corner, from which
50" Fir stump bears S.61°30'W., 72.6 ft.
50" Fir stump bears N.86°W., 31.6 ft.
(Original BTs, scribing visible)
Set new Red Cedar post for the corner, from which
New BT, 18" Red Cedar bears N.61°31'W., 52.9 ft.

Survey by Robert B. Ward Jr. - For: Champion International Corp. - Feb. 24, 1977 - C.S. File 58/139 and M 65-4

Found - Cedar post set by Stephens in 1965.
Orig. BT, now stump, a 50" Fir bears S.61°30'W., 72.6 ft.
Orig. BT, now stump, a 50" Fir bears N.86°00'W., 31.6 ft.
From the above mentioned BTs, I SET a ¾" x 36" galv. I.P. with brass cap, from which
A 20" Alder bears S.22°00'E., 22.2 ft.
An 18" Cedar bears N.61°00'W., 51.6 ft. (This is Cedar set by Stephens, bearing and distance are to my brass cap)
The Cedar post set by Stephens bears N.29°00'E., 3.1 ft. from my brass cap.