

TOWNSHIP 22 RANGE 13 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 2118)

Set post, cor. of secs. 25, 26, 35 and 36, from which
A Pine 6" dia., bears S.87½°W., 554 lks. dist.
A Pine 5" dia., bears N.89°W., 576 lks. dist.
No other bearing trees near.

BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1122 - surveyed Oct. 1982 - (DCSO records Vol. 44 Page(s) 17063)

Point for the cor. of secs. 25, 26, 35 and 36, at proportionate position. There is no remaining evidence of the original corner.

Set an aluminum rod 6 ft. long, 5/8" dia., 5 ft. in the ground, in concrete, with alum. cap mkd:

T 22 S	R 13 W
<u>S 26</u>	<u>S 25</u>
S 35	S 36
1982	

from which

A Pine 10" dia., bears S.76¼°W., 551 lks. dist. mkd. T22S R13W S35 BT.

A Spruce 19" dia., bears N.80°W., 863 lks. dist. mkd. T22S R13W S26 BT.

No suitable trees available within limits in secs. 25 & 36

Set a steel fence post alongside the alum. rod.