

TOWNSHIP 22 RANGE 13 POINT IDENTIFIER # 700536

PRIMARY CORNER DESCRIPTION Wit. Cor. to M.C. E. bdy Sec. 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #68 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 1983)

Set Witness to meander corner.
Planted post, from which
 A Spruce 100" dia., bears S.26°W., 25 lks. dist.
 A Spruce 10" dia., bears S.67°E., 27 lks. dist.

BLM resurvey by Glenn F. Goodson, Scott R. McIntyre and Scott R. McMullin, Cadastral Surveyors - Under Group #1064 - Surveyed June/Sept. 1981 - (DCSO records Vol. 44 Page(s) 17188)

Point for the witness cor. to the meander cor. of secs. 7 and 12 on the left bank of the Umpqua River, at record distance; there is no remaining evidence of the original witness corner. No permanent monument established.