

TOWNSHIP 22 RANGE 13 POINT IDENTIFIER # 700652

PRIMARY CORNER DESCRIPTION M.C. on E. bdy. Sec. 1

Alias 831010 Description M.C. Right bank Umpqua River  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by Glenn F. Goodson, Scott R. McIntyre and Scott R. McMullin, Cadastral Surveyors - Under Group #1064 - Surveyed June/Sept. 1981 - (DCSO records Vol. 44 Page(s) 17188-89)

-----  
Point for the meander cor. of secs. 1 and 6 on the right bank of the Umpqua River, at record distance; there is no remaining evidence of the original corner.

Set an aluminum post, 28" long, 2½" dia., 24" in the ground, in concrete, with alum. cap mkd.

T 22 S  
R 13 W R 12 W  
S 1 S 6

/  
/MC  
1981

No suitable trees available within limits. Set a steel fence post alongside aluminum post.

NOTE: I could find no reference to any original corner evidence in the notes furnished me. Harvey Gordon, 1857 GLO survey (DCSO records, Vol. 5 Page 1983) and Simon Cathcart, 1857 GLO survey (DCSO records, Vol. 5 Page 2011) both make reference to Right bank meander corner but do not mention any corner posts or accessories. (Virginia Laugen, Sept. 1995)

Fd. OK by McLind, June 1998 - M128-75