

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2132)

Set basalt stone 16x12x7 ins. 12" in the ground, mkd. with 5 notches on N. and 1 notch on S. edges, for cor. to secs. 25, 30, 31 and 36, from which
A Hemlock 5" dia., bears N.70°E., 40 lks. dist. mkd. T23S R1E S30 BT.
A Hemlock 9" dia., bears S.30°E., 24 lks. dist. mkd. T23S R1E S31 BT.
A Hemlock 8" dia., bears S.7°W., 38 lks. dist. mkd. T23S R1W S36 BT.
A Hemlock 14" dia., bears N.33°W., 31 lks. dist. mkd. T23S R1W S25 BT.

GLO resurvey by John G. Collins; Dan P. Mumbrue; Theodore Vander Meer, under special instructions dated May 9, 1922 - (DCSO records Vol. 5 Page(s) 2165)

The old cor. of secs. 25, 30, 31 and 36, which is a basalt stone, firmly set, 6x10x8 ins. above ground, mkd. with 5 notches on N., and 1 notch on S. edge; from which
A Hemlock 5" dia., bears N.86°E., 37 lks. dist. mkd. T23S R1E S30 BT.
A Hemlock 8" dia., bears S.23°E., 28 lks. dist. mkd. T23S R1E S31 BT.
A Hemlock 8" dia., bears S.6°W., 40 lks. dist. mkd. T23S R1W S36 BT.
A Hemlock 30" dia., bears N.35°W., 32 lks. dist. mkd. T23S R1W S25 BT.
I now change this cor. to refer to secs. 25 and 36 only, mark the stone S25 on NW.; and S36 on SW. face, and obliterate the marks on the bearing trees referring to secs. 30 and 31.

Douglas County Surveyors Office - L.E. Monrean; P.L. Earle; crew, Oct. 26, 1976 - C.S. File 59/24-44

Found - Stone, 6"x10"x8", S25 on NW. face, S36 on SW. face, four notches on N. edge (Rec. 5) and one notch on S. edge.
5" now 12" Hemlock, bears N.86°E., 24.4 ft. Scribe obliterated in 1825 resurvey.
8" now 16" Hemlock bears S.23°E., 17.1 ft. (Rec. 18.5 ft.) Scribe obliterated in 1925 resurvey.
8" Hemlock bears S.6°W., 21.1 ft., uprooted and badly rotted. Scribe mark found "S".

(Cont. Next Page)

TOWNSHIP 23 RANGE 01 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

NW. bearing tree not found.
Set 30" x 1" Iron pipe with brass cap at corner, stamped:
Douglas County Surveyor

		T 23 S	
R			R
1	S 25		1
W	S 36		E
		1976	

We place orig. stone monument on W. edge of cap.
New BT - An 8" Hemlock, bears N.35°W., 17.4 ft. Tree double
blazed and scribed "T23S R1W S25 CS BT"
There are no suitable trees to scribe in South quadrant.