

TOWNSHIP 23 RANGE 02 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2205-6)

Set a basalt stone, 14x12x10 ins., 10 ins., in the ground for 1/4 sec. cor., mkd: 1/4 on N. face; from which
A Cedar, 20" dia., bears N.30°W., 36 lks., mkd: 1/4 S BT.
A Fir, 40" dia., bears S.45°W., 32 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1969 - C.S. File 54/27-113

Found - No marked stone found.
Orig. 20", now 26" Fir, broken off, N.30°W., 23.8 ft., "1/4S" scribe on log & reverse "BT" on remains of stump.
Orig. 40", now 48" Fir, alive, S.45°W., 21.1 ft., log of turnout lying over blaze.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R2W
OFFICE S 29
1969 S 32
New BTs- 13" Hemlock N.27°E., 35.5 ft., mkd: 1/4 S29 CS BT
15" Cedar S.33°E., 24.3 ft., mkd: 1/4 S 32 CS BT
This corner lies on very steep, westerly slope.

Dan Baker - For: Weyerhaeuser Co. - Nov. 2015 - M170-28

Found - 2 1/2" Douglas Co. brass cap "1969"
30" Hemlock, N.27°E., 35.4' to center - 1969 Douglas Co. BT.
15" Cedar snag, S.33°E., 24.3' to center, 1969 Douglas Co. BT.
48" Fir stump, S.46°W., 21.0' to center, 1969 Orig. BT.
26" Cedar stump, N.30°W., 23.6' to center, Orig. BT.
New - 10" Fir S.28°E., 12.8' to center, scribed 1/4S32 BT
12" Hemlock, S.80°W. 16.1' to center, scribed 1/4S32 BT
10" Hemlock, N.3°W. 12.0' to center, scribed 1/4S29 BT
5 1/2' metal post set alongside corner.