

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2196)

-----  
Set a post 4 ft. long 4" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ on W face from which  
A Hemlock, 12" dia., bears S.30°E., 33 lks., mkd: ¼ S BT.  
A Fir, 36" dia., bears N.72°W., 38 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1969 - C.S. File 54/27-109

-----  
Found - Orig. 12" now 30" Hemlock, alive, S.30°E., 21.8 ft. scribe visible by looking into hole. We rescribe "¼ S34 CS BT"  
Orig. 36" now 46" Fir, alive N.72°W., 25.1 ft., show very good scars.  
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R2W OFFICE 1969 ¼ S 33|S 34  
15" Hemlock S.20°W., 46.3 ft. mkd: ¼ S33 CS BT  
This corner lies on very steep westerly slope in old growth timber and vine maple brush.

Helmut Kreidler - For: Weyerhaeuser Co. - Assisted by Ken Perkins - May 13, 1982 - C.S. File 58/271-1

-----  
Found - 12" now 30" Hemlock (orig.) bears S.30°E., 21.8 ft. open face scribing with Douglas Co. tag.  
36" now 46" Fir (orig.) face grown over bears N.72°W., 25.1 ft. with BLM tag.  
16" Hemlock, S.20°W., 46.3 ft. scribing visible, face open with Douglas Co. tag.  
1969 Douglas Co. brass cap.  
New BT - 60" Fir, bears S.25½°W. 40.3 ft. w/"W" nail & plate. "W" nail & plate added to 30" Hemlock.