

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 5 Page(s) 2173)

-----

Set a Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which

A Fir 40" dia., bears S.10°W., 14 lks. dist. mkd. ¼ S BT

A Hemlock 18" dia., bears N.20°E., 15 lks. dist. mkd. ¼ S BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2180-81)

-----

(39.00 chs.)

Old ¼ sec. cor. a post bears South 3.00 chains. I destroyed this post, also the marks on old bearing trees.

(40.00 chs., West)

Set a basalt stone 12x10x6 ins., 8" in the ground for ¼ sec. cor., marked ¼ on N. face, from which

A Hemlock 20" dia., bears S.76°30'E., 19 lks. dist. mkd. ¼ S BT.

A Hemlock 18" dia., bears N.4°W., 8 lks. dist. mkd. ¼ S BT.

Leonard B. Wilson, Weyerhaeuser Co. - June 3, 1969 - C.S. File 53/106-3

-----

Found - Stone in place.

20" Hemlock, S.76°30'E., 19 lks. (12.5 ft.), scribing visible. Now 30" Hemlock, added "W" nail & plate, S.82°E., 10.6 ft.

18" N.04°W., 8 lks. (5.3 ft.), scribing visible. Now 24" Hemlock snag, added "W" nail & plate, N.05°W., 4.2 ft.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 1969 - C.S. File 54/27-164

-----

Found - Corner stone with partial "¼", "4" chipped off.

20" now 30" Hemlock, alive, S.76½°E., 12.5 ft., shows good scar.

18" now 22" Hemlock, dead, N.4°W., 5.3 ft., scribe visible on unhealed blaze.

Set Brass cap at cor. mkd: County Surveyors Office  
(Reset stone alongside) T23S R2W ¼ S 34  
T24S S 3

(Cont. Next Page) 1969

TOWNSHIP 23 RANGE 02 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 34; & 3, T24-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 8" Hemlock N.22°W., 49.4 ft. mkd. "¼ S34 CS BT".  
12" Hemlock S.82°W., 28.1 ft. mkd. "¼ S3 CS BT".  
Brass cap lies toward easterly end of rootwad of NE orig. BT.  
Corner lies about 160 ft. West of creek, 2 ft. wide, course SW.

Russell Badgley - For: Weyerhaeuser - 10/2021 - M178-42

Found - A 1½" iron pipe by DCSO in 1969, firmly set and projecting 4" above the ground, with a 2½" brass cap (properly) marked:

From which BTs by Chandler in 1893 -

A root hole bears N.86°45'E., 12.0 ft (S.76°30'E., 12.5')

A rotten stump bears N.8°30'W., 5.2 FT (N.4°00'W., 5.3')

And BTs by others -

A 18" Hemlock bears N.0°45'W., 32.6 ft w/healed blaze (no record)

New BTs- A 13" Hemlock bears N.37°15'E., 25.0 ft scribed "¼ S34 BT" on double blaze

A 12" Hemlock bears S.36°15'E., 31.2 ft scribed "¼ S4 BT" on double blaze

NAD83 (2011)

LATITUDE 43°31'16.91213"N LONGITUDE 122°55'21.42448"W