

TOWNSHIP 23 RANGE 02 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2197-8)

Set basalt stone, 18x8x6 ins. 14" in the ground for ¼ sec. cor. mkd: ¼ on N face, from which
A Fir, 36" dia., bears N.47°W., 22 lks., mkd: ¼ S BT.
A Fir, 36" dia., bears S.35°E., 14 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1969 - C.S. File 54/27-102

Found - 1¼" alum. pipe (unrecorded) at corner & probable corner stone.
Orig. 36" now 38" Fir alive, N.47°W., 14.5 ft., shows good scar.
Orig. 36" now 37" Fir snag, 20 ft. high, S.35°E., 9.2 ft., we open & find "¼S" scribe.
No marks found on corner stone.

DO NOT SET BRASS CAP

New BTs- 10" Hemlock N.42°E., 42.3 ft., mkd: ¼ S27 CS BT.
(This BT lies on south bank of creek)
18" Hemlock S.89°W., 36.1 ft. mkd: ¼ S34 CS BT.
This corner lie on steep north slope 50 ft. S of creek 3 ft. wide.