

TOWNSHIP 23 RANGE 02 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2192-3)

Set basalt stone, 18x14x5 ins. 14" in the ground for cor. to secs. 26, 27, 34, & 35, marked with 1 notch on S and 2 notches on E edges, from which
A Fir, 36" dia., bears N.57°E., 49 lks., mkd: T23S R2W S26 BT.
A Hemlock, 12" dia., bears S.15°E., 10 lks., mkd: T23S R2W S35 BT.
A Cedar, 15" dia., bears S.57°W., 20 lks., mkd: T23S R2W S34 BT.
A Fir, 40" dia., bears N.45°W., 16 lks., mkd: T23S R2W S27 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1969 - C.S. File 54/27-100

Found - Probable corner stone, broken in several pieces.
Unrecorded 3/4" iron rod, 24" long at corner point.
Orig. 36" now 40" Fir N.57°E., 32.3 ft. alive.
Orig. 12" now 15" Hemlock, alive, S.15°E., 6.6 ft. scribe visible. Rescribed: "T23S R2W S34 CS BT"
Orig. 15" now 21" Cedar, alive, S.57°W., 13.2 ft., scribe visible. Rescribed: "T23S R2W S34 CS BT"
Orig. 40" now 48" Fir, alive, N.45°W., 10.6 ft., shows good scar.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R2W
OFFICE S 27 | S 26
1969 S 34 | S 35
New BT- 13" Hemlock N.50°E. 35.7 ft. mkd: T23S R2W S26 CS BT
This corner lies 190 ft. W. of creek, course NW & 50 ft. E.
Top of rounded spur, sloping North.