

TOWNSHIP 23 RANGE 02 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619 dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2189)

Set a post 4 ft. long 4" sq. 24" in the ground for cor. to secs. 25, 26, 35, & 36 mkd. T23S S25 on NE, R2W S36 on SE, S35 on SW, and S26 on NW, faces with 1 notch on S & E edges from which

- A Fir, 50" dia., bears N.28°E., 15 lks., mkd: T23S R2W S25 BT.
- A Cedar, 20" dia., bears S.70°E., 57 lks., mkd: T23S R2W S36 BT.
- A Fir, 40" dia., bears S.26°W., 20 lks., mkd: T23S R2W S35 BT.
- A Hemlock, 4" dia., bears N.66°W., 17 lks., mkd: T23S R2W S26 BT.

Georgia Pacific Timber Co. - Sept. 1962, added 1/5/2012 - C.S. File 65/76-3

- Found - 6" hem. N.63°W., 11.0 BT
60" fir N.28°E., 9.5 BT BK tag.
60" fir S.26°W., 9.0 BT BK tag.
26" Cedar S.70°E., 37.0 ft.
Set - 1½" IP

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1969 - C.S. File 54/27-105

- Found - Orig. 50" Fir, now 56" stump, N.28°E., 9.9 ft., shows scars.
Orig. 20" Cedar, now 22" snag, S.70°E., 37.6 ft., scribe visible.
Orig. 40" Fir, now 50" shattered stump, S.26°W., 13.2 ft.
No trace of NW 4" Hemlock BT.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R2W
OFFICE S 26 | S 25
1969 S 35 | S 36
10" Hemlock S.61°W., 29.5 ft. mkd: T23S R2W S35 CSBT
18" Hemlock S.9°E., 38.4 ft. mkd: T23S R2W S36 CS BT
8" Hemlock N.16°W., 92.2 ft. mkd: T23S R2W S26 CS BT
No tree available in sec. 25 due to logging.

Fd. Ok by Douglas Co. Surveyors Office - Karen Reed 3/13/1979 - C.S. File 60/24-18