

PRIMARY CORNER DESCRIPTION 1/4 Secs. 25; & 30 T23-1

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 5 Page(s) 2128)</p> <p>-----</p> <p>Set hemlock post, 3 ft. long 3" sq., 24" in the ground for ¼ sec. corner marked ¼ S on W face, from which</p> <p> A fir, 8" dia., bears S.60°E., 8 lks., mkd: ¼ S BT.</p> <p> A fir, 5" dia., bears West, 14 lks., mkd: ¼ S BT</p>
<p>GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 5 Page(s) 2130-1)</p> <p>-----</p> <p>(Pg. 2130) Could find no trace of old ¼ sec. cor.</p> <p>(Pg. 2131) Set basalt stone 12x12x6", 9" in the ground, mkd. ¼ on W face for ¼ sec. cor. on old blazed line, from which</p> <p> A fir, 7" dia., bears S.41½°W., 16 lks., mkd: ¼ S BT.</p> <p> A hemlock, 7" dia., bears S.17½°E., 28 lks., mkd: ¼ S BT.</p>
<p>Georgia Pacific Timber Co. - Sept. 1962, added 1/5/2012 - C.S. File 65/76-3</p> <p>-----</p> <p>Found - 1½ IP</p> <p> 24" Fir S.70°W., 4.0 BK tag</p> <p> 12" Hem S.17°E., 18.5 BK tag.</p>
<p>Dan Baker - For: Weyerhaeuser Co. - 9/2021 - C.S. 65/76-1</p> <p>-----</p> <p>Found - 1½ iron pipe (bent)</p> <p> 17" hemlock stump S.13°E., 18.7' - original BT</p> <p> 24" fir stump S.64°W., 4.2' (Booth Kelly BT)</p> <p> Nothing set</p> <p>New - 16" Fir, N.51°E., 34.5' to spike in side - scribed "¼ S30 BT"</p> <p> 12" cedar, S.21°E., 19.5' to spike in side - scribed "¼ S30 BT"</p> <p> 21" fir, S.83°W., 19.7' to spike in side - scribed "¼ S25 BT"</p> <p> 15" fir N.13°W., 19.5' to spike in side - scribed "¼ S25 BT"</p>
<p>Dan Baker - For: Weyerhaeuser Co. - 11/2021 - M180-19</p> <p>-----</p> <p>Condition report</p> <p>Found - 1½ iron pipe (bent)</p> <p> 17" rotten hemlock stump, S.13°E., 18.7' to center</p> <p> OBT</p> <p>continued next page</p>

TOWNSHIP 23 RANGE 02 POINT IDENTIFIER # 700240

PRIMARY CORNER DESCRIPTION 1/4 Secs 25; & 30 T23-1

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

24" rotten fir stump, S.64°W., 4.2' to center.
19" fir, N.51°E., 34.5' to spike side/center
16" cedar, S21 E, 19.5' to spike side/center
24" fir, S.83°W., 19.7' to spike side/center
17" fir, N.13°W., 19.5' to spike side/center