

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by James P. Currin, Deputy Surveyor, under contract #438, dated May 3, 1882 - (DCSO records Vol. 6 Page(s) 2252-3)

-
- A Yew, 5" dia., which I mark: T23S S29 on NE, R3W S32 on SE, S31 on SW, and S30 on NW, faces with 1 notches on S and 5 notches on E sides from which
- A Cedar, 28" dia., bears N.40°E., 45 lks., mkd: T23S R3W S29 BT.
 - A Hemlock, 6" dia., bears S.55°E., 34 lks., mkd: T23S R3W S32 BT.
 - A Hemlock, 40" dia., bears S.3°W., 65 lks., mkd: T23S R3W S31 BT.
 - A Hemlock, 30" dia., bears N.25°W., 40 lks., mkd: T23S R3W S30 BT.

Gilbert A. Gardner - June 2, 1954 - C.S. File 53/1

-
- Found - SW Hemlock BT, chopped out, scribe plainly visible. Cedar & NE Hemlock located. Hemlock still standing, but nearly dead; bears visible scar.
- New BTs-
- 16" Cedar bears N.74°W., 52.5 ft. mkd: S30 BT
 - 32" Cedar bears S.28°W., 65.0 ft. mkd: S32 BT
 - 18" Hemlock bears 30°W., 51.4 ft. mkd: S31 BT
 - 20" Cedar bears N.27°E., 80.5 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Nov. 1967 - C.S. File 54/16-52

-
- Found - Orig. 28" Cedar, now 53" stump N.40°E., 29.7 ft., reverse face & axe notch visible on top of stump, N.40°E., 29.7 ft., reverse face & axe notch visible on top of stump.
- (Possible orig.) 6" now 18" Hemlock, S.49°E., (rec. S.55°E.) 22.4 ft., alive, no scar shown. (We scribe "T23S R3W S32 CS BT"
- Orig. 40" Hemlock, now 50" stump, S.3°W., 42.9 ft., "31" visible. Open lower & find "BT" scribe.
- Orig. 30" Hemlock, now 42" stump, N.25°W., 26.4 ft., shows scar.
- 1954 renewal
- 32" Cedar S.32°E., (not S.28°W.) 65.0 ft., now stump "S32BT".
 - 20" Cedar N.27°E., 81.7 ft. (not 80.5 ft.) "S29BT"
- Gardner's NW BT gone completely & SW BT down. This corner lies on East slope approx. 150' W. of small ravine, course N.
- continued next page

TOWNSHIP 23 RANGE 03 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R3W OFFICE S 30 S 29 1999 S 31 S 32 Set 6' steel fence post alongside brass cap.</p>
<p>Dave Wellman - For: Weyerhaeuser Co. - Erin Heatherstone & Micah Johnstone - June 2003 - C.S. File 65/45-37 A&B ----- Found - 1 3/4" iron pipe with 1967 Douglas Co. brass cap - 0.3 ft. AGL 53" Cedar stump, N.44°E., 31.1 ft. to spike set side center - New WEYCO tag set. 26" Hemlock, S.45°E., 23.7 ft. to spike set side center - New WEYCO tag set. 50" Hemlock stump, 1967 Douglas Co. tag reads N.3°E., 42.9 ft. NW Hemlock BT fd. rotten. 32" Cedar stump, 1967 Douglas Co. Tag reads N.32°W., 65.0 ft. 21" Cedar, 1967 Douglas Co tag reads S.27°W. 81.7 ft New - 26" Fir, N.55°W., 9.1 ft. to spike set side center scribed S 30 BT Corner lies approx. 150 ft. west of a ravine.</p>
<p> </p>