

PRIMARY CORNER DESCRIPTION Sec Cor for 35 & 36; 1 & 2, T24-3

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by James P. Currin, Deputy Surveyor, under Contract #438, dated May 2, 1882 - (DCSO records Vol. 5 Page(s) 2215)

A Hemlock 10" dia., which I marked T23S R3W S36 on NE.; T24S R3W S1 on SE.; T24S R3W S2 on SW.; and T23S R3W S35 on NE. faces with 1 notch on E. and 5 notches on W. faces for cor. to secs. 1, 2, 35 and 36, from which

- A Hemlock 6" dia., bears N.60°W., 14 lks. dist. mkd. T23S R3W S35 BT.
- A Hemlock 6" dia., bears N.30°E., 39 lks. dist. mkd. T23S R3W S36 BT.
- A Cedar 24" dia., bears S.1°E., 32 lks. dist. mkd. T24S R3W S1 BT.
- A Cedar 20" dia., bears S.70°W., 49 lks. dist. mkd. T24S R3W S2 BT.

D.H. Jordon - Weyerhaeuser Co. - Sept. 25, 1964 - C.S. File 53/111-2

Found - 1882 10" Hemlock corner tree, now 24" windthrown, faces grown over.

- No evidence of NW. or NE. orig. BTs.
- 24" Cedar, now 12 ft. snag, scribing visible, S.1°E., 32 lks. (21.1 ft.)
- 20" Cedar, now 24" Cedar, standing, face chopped out, scribing visible, S.70°W., 49 lks. (32.3 ft.)

Accessories added this date:

- 11" Hemlock S.19°45'W., 18.1 ft. "W" nail & plate.
- 30" Cedar S.77°15'W., 25.8 ft. (orig. BT) with "W" nail and plate.
- 9" Hemlock N.35°E., 10.0 ft. "W" nail and plate.
- 24" Cedar N.56°E., 53.7 ft. "W" nail and plate.

Bruce Wood - Weyerhaeuser Co. - March 23, 1965 - C.S. File 53/111-27

Found - 1882 corner tree, 24" wind thrown stump with faces overgrown.

- No evidence of orig. NW., NE., or SW. BTs.
- 24" Cedar S.01°E., 32 lks. (21.1 ft.), splintered by logging, faces gone. (Orig. BT)

Accessories added this date:

- 11" hemlock stump S.19°45'W., 18.1 ft. "W" nail & plate.

(Cont. Next Page)

