

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T23-5

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by - James E. Freeman Deputy Surveyor, under Contract #1, dated May, 28, 1851 (DCSO records Vol. 6 Page(s) 2331)

Set ¼ sec. post, from which
 A Laurel 12" dia., bears S.35°E., 10 lks. dist.
 A Fir 17" dia., bears N.20°W., 40 lks. dist.

O.F. Thiel - Feb. 1927 (Recorded 8/26/1998) - F.B. 116 Pg. 19

SE BT gone but a younger in place of old. Marked the new tree.

Douglas Co. Surveyors Office, Milo Godfrey, Deputy - Vernon Tracy, Mike Stone, crew - April 25, 1963 - C.S. File 53/9-122

Found - 1¼" Iron pipe.
 Uprooted and partly rotted Fir, N.20°W., 26.4 ft.
 Cut open and found good scribing "¼"
 Laurel sprouts, with rotten Laurel log lying on ground, S.35°E., 6.6 ft. Did not look for scribing in Laurel.
Did not set brass cap. Iron pipe in good condition.
New BTs -8" D.Fir S.60°W., 13.3 ft. mkd. ¼ S24 CS BT.
 9" Yew N.12°E., 85.4 ft. mkd. ¼ S19 CS BT.

Mark Smalley - For: Roseburg Resources - Oct. | Nov. 2002 - M137-55

Found - 1¼" iron pipe renewed by Douglas Co Surveyor in 1963
BTs - 22" Fir S.60°W 13.3' healed.
 10" Yew N.12°E., 85.4' scribe visible.
Scribed- 10" Fir N.82°W., 17.0' "¼S BT"
 10" Fir S.11°E., 20.4' "¼S BT"

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2147, surveyed Aug/Nov. 2006 - (DCSO rec. Vol. 55 Page(s) 21408-9)

The ¼ sec. cor. of secs. 19 & 24, perpetuated by Thiel, of the Douglas County Surveyor's Office, in 1927, further perpetuated by Godfrey, in 1963, further perpetuated by Smalley, in 2002, monumented with an iron pipe, 1½" dia., firmly set, projecting 12" above the ground, from which the remains of the original bearing trees
 A madrone sprout, 9" dia., bears S.21°E., 6.6 ft , with no marks visible. (Record, S.35°E.)
continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T23-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed fir stump, 25" dia., bears N.20°W., 26.4 ft., with axe marks visible.
and bearing trees mkd. by Godfrey
A yew, 10" dia., bears N.12¼°E., 85.3 ft., with scribe marks ¼ S19 CS BT visible on a partially healed blaze.
A fir, 23" dia. bears S.60°W. 12.9 ft. with a healed blaze and bearing trees mkd. by Smalley
A fir, 10" dia., bears S.12¼°E., 20.4 ft. with fragmentary scribe marks visible on a partially healed blaze.
A fir, 10" dia., bears N.84°W., 17.0 ft., with fragmentary scribe marks visible on a partially healed blaze.
At the corner point
Cement a brass cap, 3" dia., with 3½" stem, on top of iron pipe, mkd.
T 23 S
¼
R5W R4W
S 24|S 19
2006