

PRIMARY CORNER DESCRIPTION Cor. Secs 17, 18, 19, & 20

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Original - William P. Wright, Deputy Surveyor, under Contract No. 514, dated Aug. 27, 1884 (DCSO records Vol. 6 Page(s) 2311)

-----

Set post 6" dia., 4 ft. long, with marked stone 12" in ground for cor. to secs. 17, 18, 19, & 20 mkd: T23S S17 on NE, R4W S20 on SE, S19 on SW, S18 on NW face with 5 notches on E and 3 on S edges, from which

- A Fir, 10" dia., bears N.69°W., 47 lks., mkd: T23S R4W S18 BT.
- A Fir, 10" dia., bears S.71°E., 71 lks., T23S R4W S20 BT.
- A fir, 24" dia., bears N.42°E., 83 lks., mkd: T23S R4W S17 BT.
- A Fir, 24" dia., bears S.59°W., 38 lks., mkd: T23S R4W S19 BT.

Douglas Co. Surveyors Office - James Byron - Milo Godfrey & S.A. Bilow - Jan. 8, 1959 - C.S. File 49/42-6

-----

Found - Axle at corner & all BTs.  
Orig. 24", now 44" Fir, N.42°E., 54.8 ft., probably bark scribed, bark burned, no scribing found.  
Orig. 24", now 44" stump, S.59°W., 25.1 ft., no scribing found.  
good Orig. 10", now 20" Fir, N.69°W., 31.0 ft., shows bark scribing "S18".  
Orig. 10", now 20" Fir, S.71°E., 46.9 ft., shows scar, I do not open.

Note - Corner is in the corner of a new fence running west & north.

I re-scribe orig. BTs:  
Now 44" R.Fir, N.42°E., 54.8 ft., scribed S17 T23S R4W CS BT.  
Now 20" R.Fir, S.71°E., 46.9 ft., scribed S20 T23S R4W CS BT.  
Now 20" Fir, N.69°W., 31.0 ft., scribed S18 T23S R4W CS BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Stone - Jerry Layne - Oct. 1965 - C.S. File 54/16-9

-----

Found - 1 3/4" axle shaft, 14" above ground at fence corner N & W.  
NE BT, now stump - pushed out of place.  
Other BTs recorded in 1959 in good condition, as follows:  
(Cont. next page)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 20" R.Fir, S.71°E., 46.9 ft., scribing visible.  
20" R.Fir, N.69°W., 31.0 ft., scribing visible.  
17" D.Fir, S.84°W., 80.0 ft., scribing visible.  
8" R.Cedar, N.2°E., 262.0 ft., scribing visible.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #895 - Surveyed June/Sept. 1976 (DCS0 records Vol. 41 Page(s) 16165-66)

-----

The cor. of secs. 17, 18, 19, & 20, perpetuated and recorded by Byron in 1959, and further perpetuated by Tracy in 1965, monumented with an axle, 1 3/4" dia., firmly set, projecting 12" above ground, from which the remains of the orig. BTs:

- A sawed Fir stump, 44" dia., bears N.47°E., 83 lks., rescribed by Byron in 1959, with scribe marks: T23S R4W S17 CS BT visible on open blaze. (Record N.42°E.)
- A Fir snag, 18" dia., bears S.69 3/4°E., 73 lks., rescribed by Byron in 1959, with scribe marks: T23S R4W S20 CS BT visible on open blaze. (Rec. S.71°E., 71 lks)
- A sawed Fir stump, 42" dia., bears S.59°W., 38 lks., no marks visible.
- A Fir, 22" dia., bears N.69°W., 47 lks., rescribed by Byron in 1959, with scribe marks: T23S W S visible on bark blaze.

and BTs mkd. by Tracy

- A Cedar, 12" dia., bears N.3 1/2°E., 395 lks, with fragmentary scribe marks visible on open blaze.
- A Fir, 19" dia., bears S.84 3/4°W., 121 1/2 lks., with scribe marks T23S R4W S19 CS BT visible on open blaze.

At corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T23S	R4W
S 18	S 17
S 19	S 20
1976	

from which new BTs:

- A Fir, 5" dia., bears N.27 3/4°E., 48 lks., mkd: T23S R4W S17 BT.
- A Fir, 6" dia., bears S.55 1/4°E., 32 1/2 lks., mkd: T23S R4W S20 BT.
- A Fir, 4" dia., bears S.4°W., 20 lks., mkd: T23S R4W S20 BT.

Reset axle alongside iron post.

FD. BC & 6 BTs by D. Edwards, 3/2008 - M155-14

continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 17, 18, 19, & 20

Alias	Description

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2147, surveyed Aug/Nov. 2006 - (DCSO rec. Vol. 55 Page(s) 21416-7)

-----  
The cor. of secs. 17, 18, 19, and 20, monumented with an iron post, 2½" dia., firmly set, projecting 2 ins. above the ground, (alongside of which is an axle, 1¾" dia., splines up, firmly set, projecting 5" above the ground, origin unknown), with brass cap (properly) mkd.

from which the remains of the original bearing trees, rescribed by Byron, in 1959, reported by Jelley in 1976

A sawed fir stump, 40" dia., bears N.47°E., 54.8 ft., with scribe marks T23S R4W S17 CS visible on a partially healed blaze.

A decayed fir snag, 14" dia., bears S. 69¾°E., 48.2 ft., with scribe marks R4W S20 CS visible on partially healed blaze.

A sawed and decayed fir stump, 45" dia., bears S.59°W., 25.1 ft., no marks visible.

A fir, 31" dia. bears N.69°W. 31.0 ft. with a healed blaze and bearing trees mkd. by Tracy, in 1965, reported by Jelley in 1976

A cedar, 32" dia., bears N.3½°E., 260.7 ft., with a healed blaze.

A fir, 24" dia., bears S.84¾°W., 80.2 ft. with fragmentary scribe marks visible on a partially healed blaze. and bearing trees mkd. by Jelley in 1976

A fir, 15" dia. bears N.27¾°E. 31.7 ft with a healed blaze

A fir, 15" dia. bears S.55¼°E. 21.5 ft with a healed blaze

A fir, 16" dia. bears S.4°W., 13.2 ft. with a healed blaze

Corner is located at cor. of barbed wire fences extending N & W

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group No. 2172 - Surveyed July/Nov. 2007 - (DCSO records Vol. 55 Page(s) 21544-5)

-----  
The cor. of secs. 17, 18, 19, and 20, monumented with an iron post, 2½" dia., firmly set, projecting 2" above the ground (with an axle, 1¾" dia., firmly set, projecting 6" above the ground, alongside), with brass cap (properly) mkd.

from which the remains of the original bearing trees

A sawed fir stump, 52" dia., bears N.47°E., 54.8 ft., with scribe marks T23S R4W S17 CS BT visible on an open blaze

A fir snag, 13" dia., bears S.69¾°E., 48.2 ft., with scribe marks T23S R4W S20 CS visible on an open blaze.

continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Cor. Secs. 17, 18, 19, & 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed fir stump, 46" dia., bears S.59°W., 25.1 ft., with no marks visible.  
A fir, 30" dia., bears N.69°W., 31.0 ft., with a healed blaze.  
and bearing trees mkd. by Tracy, in 1965, reported by Jelley  
A cedar, 33" dia., bears N.3½°E., 260.7 ft., with a healed blaze.  
A fir, 27" dia., bears S.84¾°W., 80.2 ft., with fragmentary scribe marks visible on a partially healed blaze.  
and bearing trees mkd. by Jelley  
A fir, 16" dia., bears N.27¾°E., 31.7 ft., with a healed blaze.  
A fir, 16" dia., bears S.55¼°E., 21.4 ft., with a healed blaze.  
A fir, 16" dia., bears S.4°W., 13.2 ft., with a healed blaze.  
Corner is located 1.0 ft. E. of a fence cor. with 5 strand barbed wire fences extending North and West.