

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855  
(DCSO records Vol. 6 Page(s) 2287)

-----  
Set 1/4 Sec. post from which  
A Fir, 20" dia., bears S.22°W., 6 lks.  
A Fir, 6" dia., bears N.49°W., 22 lks.

BLM resurvey by C. Albert White & Donald R. Beck, Cadastral  
Surveyors, under Group #243 & #350 - Surveyed April/June 1963  
(DCSO records Vol. 32 Page(s) 13272)

-----  
The 1/4 sec. cor. of secs 20 & 29, determined at the record  
dist. from the remains of the orig. BT:

A Fir stump hole, bears N.44°W., 22 lks., with no marks  
remaining. (Rec. bearing N.49°W.)

A burned Fir stump, 20" dia., bears S.25°W., 6 lks., with  
no marks remaining. (Rec. bearing, S.22°W.)

and a BT not of record:

A Fir snag, 28" dia., bears S.61°E., 21 lks., mkd: 1/4 on  
open blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with  
brass cap mkd:

1/4  $\frac{S\ 20}{S\ 29}$   
T23S R4W  
1963

from which new BTs:

A sawed Fir stump, 48" dia., bears N.67°W., 96 lks., mkd:  
1/4 S20 BT.

A sawed Cedar stump, 30" dia., bears S.68°W., 76 lks.,  
mkd: 1/4 S29 BT.

The corner is situated on a SE slope, in logged and burned  
area, 5 lks., W. of a barbed wire fence which bears N & S.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under  
Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41  
Page(s) 16161-62)

-----  
From the 1/4 secs. cor. of secs. 20 & 29, monumented with an  
iron post, 2 1/2" dia., firmly set, projecting 4" above  
ground, with properly marked brass cap, from which the  
remains of BTs mkd. by White & Beck in 1963:

A sawed Fir stump, 48' dia., bears N.67°W., 96 lks.,  
with scribe marks 1/4 S20 BT visible on open blaze.

A sawed Cedar stump, 30" dia., bears S.68°W., 76 lks.,  
with scribe marks S29 BT visible on open blaze.

and new BTs:

(Cont. next page)

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Grand Fir, 10" dia. bears N.58°W., 110½ lks., mkd: ¼  
S20 BT.  
A Fir, 4" dia., bears S.1½°W., 51 lks., mkd: ¼ S29 BT.

BLM Resurvey, by Dale B. Bedell, Cadastral Surveyor,  
Surveyed under Group No. 1601. surveyed June. 1991 thru  
July 1992. (D.C.S.O. records Vol. 51 Page(s)19375-76)

-----  
The 1/4 sec. cor. of secs. 20 and 29, monumented with an iron  
post, 2 1/2 ins. diam., firmly set, projecting 8 ins. above  
the ground, with brass cap mkd.

¼ S 20  
S 29  
T23S R4W  
1963

from which the remains of bearing trees mkd. by White and  
Beck A cedar stump, 30 ins. diam., bears S. 68° W., 76 lks.  
dist., with scribe marks 1/4 S BT visible on a rotted  
blaze.

A fir stump, 45 ins. diam., bears N. 67° W., 96 lks.  
dist., with scribe marks 1/4 S20 BT visible on a rotted  
blaze.

and bearing trees mkd. by James E. Jelley

A fir, 16 ins. diam., bears S. 3 1/2° W., 51 lks. dist.,  
with healed blaze. (Record, S. 1½° W.)

A fir, 17 ins. diam., bears N. 56 1/2° W., 110 1/2 lks.  
dist., with healed blaze. (Record, N. 58° W.)

The corner is located in the intersection of old wire fence  
lines extending N., S., and W.