

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>Original - Gordon &amp; Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 6 Page(s) 2282)</p> <p>-----</p> <p>Set ¼ Sec. post from which A Fir, 18" dia., bears N.15°E., 43 lks. A Laurel, 4" dia., bears South, 82 lks.</p>
<p>Douglas Co. Surveyors Office - Arthur Boyer, Co. Surveyor - J.H. Wittmeyer &amp; Chas. Neal, Witnesses - Dec. 30, 1937 &amp; Jan. 1, 1938 - "Old" Cor. Vol. 1, Renewed Corners - C.S. 30/52</p> <p>-----</p> <p>Set from Laurel clump for orig. BT to S. &amp; stump hole to N. Set - 4"x4" Cedar post from which: 23" Fir, bears N.43°E. ? 33" Fir, bears S.71°E. ?</p>
<p>O.F. Thiel - Year unknown - C.S. File 61/5</p> <p>-----</p> <p>Marked - Fir, 20" S.28°W., 11 (lks.?) Cedar, 20" N.60°W., 42 (lks.?)</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - Feb./March 1963 - C.S. File 53/9-8</p> <p>-----</p> <p>Found - Old scribed wooden stake in fence corner, "¼ S9" on N. side, other sides burned. 36" Fir stump bears S.71°E., 44.0 ft., good scribing visible "BT". 23" Fir snag N.20°E., 42.8 ft., not N.43°E., good scribing visible. Scribing face definitely faces fence corner &amp; not direction as called for in notes, scribing appears same age as scribing on stump to SE. A depression in ground, possible stump hole, bears N.15°E., 43 lks. (Fits call for Orig. NE BT)</p> <p>Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R4W OFFICE 1963 ¼ S9/S16</p> <p>No live trees within 500 ft. of corner.</p>
<p>BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor &amp; Robert Browning, Surveying Technician under Group #1955, surveyed 2000/2001 (DCSO rec. Vol. 54 pg(s) 20863)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 9 &amp; 16, perpetuated from original evidence no longer in existence, by Boyer, in 1938, further perpetuated by Godfrey, in 1963, monumented with an iron post, 1¼ ins. diam., firmly set, projecting 5 ins. above the ground, with brass cap (properly) mkd. continued next page</p>

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of bearing trees mkd. by Boyer  
A fir snag, 23" dia., bears N.21°E., 42.4 ft., with scribe marks ¼ S visible.

A sawed & decayed fir stump, 36" dia., bears S.69½°E., 44.6 ft., with scribe marks BT visible.

and new bearing trees

A fir, 6" dia., bears N. 76¾° E., 24.5 ft., mkd. X BT.

A fir, 9" dia., bears S. 44° E., 25.2 ft., mkd. ¼ S16 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Corner is located N. 45° E., 6.0 ft. from the corner of woven wire fences, unmaintained fences extending north, south and east.