

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - William P. Wright, Deputy Surveyor, under Contract No. 514, dated Aug. 27, 1884 (DCSO records Vol. 6 Page(s) 2307)

-----

Set post 4" dia., 4 ft. long, with marked stone 12" in ground for 1/4 sec. cor. mkd: 1/4 S on W face, from which  
A Fir, 24" dia., bears N.85°W., 42 lks., mkd: 1/4 S BT.  
A Fir, 40" dia., bears S.45°E., 3 lks., mkd: 1/4 S BT.

Wilford N. Haines - Approx. 1960 filed 12/1965 - C.S. File 54/16-23

-----

Found - 24" Fir N.85°W., 27.72 ft., bark scribed. Came back later & scribe was chopped out.  
Stump of 40" Fir, S.45°E., 1.98 ft.  
Rescribed -  
Bark, 24" now 36" Fir, N.85°W., 27.7 ft.  
Scribed- 12" I.Cedar, S.69°E., 23.5 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy & Crew - Nov. 1965 - C.S. File 54/16-19 (added 3/13/2018)

-----

Found - Haines "T" iron & 3/4" I.Pipe at cor & BTs as follows:  
48" D.Fir N.85°W., 27.7 ft. (face) bark scribed "363 1/4 S27 BT" No orig. scribe fd by us - could be orig. 40" BT  
14" R.Cedar S.69°E., 23.5 ft (center) 1/4 S26 BT" in wood  
Burned & rotted stump of fir S.45°E., 2.0 ft. No scribe fd.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy & Crew - Sept. 1966 - C.S. File 54/16-24

-----

Found - Haines' "T" iron & 3/4" IP at corner See Haines 1960  
Orig. 24" now 48" D.Fir, N.85°W., 27.7 ft., re-bark scribed. Alive.  
Orig. 40" now badly decayed remnant of burned stump, S.45°E., 2.0 ft., no scribe found.  
12" now 14" I.Cedar S.69°E., 23.5 ft., scribed with Haines' button on face. Cracked from the ground up, beginning to rot.  
DO NOT SET BRASS CAP  
New BTs- 10" I.Cedar N.54°W., 40.4 ft., mkd: 1/4 S27 BT.  
24" I.Cedar S.49 1/4°E., 26.5 ft., mkd: 1/4 S26 CS BT.  
Note - This corner lies on S. slope of spur, course SW.

(Cont. next page)

1

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41 Page(s) 16138)

-----

The 1/4 sec. cor. perpetuated and recorded by Haines in 1960 and further perpetuated by Tracy in 1966, monumented with a 1" "T" shaped iron rod, firmly set, projecting 10" above ground, from which the remains of the OBTs:

A Fir, 42" dia., bears N.85°W., 42 lks., with scribe marks BT visible on bark blaze, and scribe marks 1/4 S26 BT visible on open blaze.

and BTs mkd. by Tracy

A Cedar, 25" dia., bears S.50 3/4°E., 40 1/2 lks., with scribe marks 1/4 S26 CS BT visible on open blaze.

A Cedar, 10" dia., bears N.55°W., 60 1/2 lks., with scribe marks 1/4 S27 BT visible on open blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

<sup>1/4</sup>  
S 27 | S 26  
T 23 S R 4 W  
1976

Reset "T" shaped iron rod alongside iron post.

Ken Hoffine, LS 2291 - For: Lone Rock Timber Co. - Jan. 1990 - M 109-56 - C.S. File 63/106

-----

Corner Report

Found - 1976 2 1/4" BLM brass cap with Haines' 3/4" T-iron and identification button on top of bar and a 3/4" iron pipe and the following accessories:

Orig. 24" D.Fir, now a 42" bears N.85°W., 28.0 ft., scribe marks on bark blaze, nearly grown over open blaze visible.

Orig. 40" D.Fir badly decayed and burned remains and stump hole bears S.45°E., 2.0 ft.

27" I.Cedar, bears S.50°E., 26.5 ft., well healed face and BLM tag.

10" I.Cedar, bears N.55°W., 40.4 ft., visible scribing and BLM tag.

12" I.Cedar, bears N.68°W., 23.1 ft., (Rec. S.68°E.) visible scribing and BLM tag.

Corner lies on south facing ridge approx. 70 ft. below a wide flat bench and approx. 1150 ft. south of BLM gravel road.

continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Daniel A Renton, Minister-Glaeser Surveying - Garrett Finch & Crew - For: US Department of Interior, BLM - Great Expectation and Fast Lane -Task B -Jan 18, 2023 - M178-72 A-F

-----  
Found - 3/4" BLM brass cap (properly mkd) 0.3 ft above ground in good condition with 3/4" iron pipe SW and alongside, and a 1" Haines brass cap NW and alongside from which:  
28" Cedar bears N.40°W., 21.8 ft to side center, scabbed blaze with blank location poster (no rec)  
14" Cedar bears N.44°W., 40.1 ft to side center, with BT sign, no visible blazing (1966)  
44" Fir bears N.78°W., 28.1 ft to side center, scabbed blaze, and bark scribe with BT sign and Haines washer (1884 & 1960)  
34" Cedar bears S.54°E., 25.7 ft to side center, scabbed blaze with BT sign (1966)  
Set chaining nail at side center, BT signs on front and rear, and painted red band for existing BTs