

Alias	Description

Original - William P. Wright, Deputy Surveyor, under Contract No. 514, dated Aug. 27, 1884 (DCSO records Vol. 6 Page(s) 2301 - 02)

-----

Set post 4" dia., 4 ft. long with marked stone 12" in ground for cor., mkd: T23S S25 on NE, R4W S36 on SE, S35 on SW, S26 on NW, face with one notch in E & S edges from which

- A Fir, 36" dia., bears N.5°W., 335 lks., mkd: T23S R4W S26 BT.
- A Fir, 36" dia., bears N.19°E., 155 lks., mkd: T23S R4W S25 BT.
- A Fir, 48" dia., bears S.75°W., 172 lks., mkd: T23S R4W S26 BT.
- A Fir, 6" dia., bears S.49½°E., 112 lks., mkd: T23S R4W S36 BT.

Fd. & used in GLO survey - Carl S. Nicklin, Deputy Surveyor, under Contract No. 664, dated May 23, 1896 (DCSO records Vol. 6 Page(s) 2324)

Wilford N. Haines - Approx. 1960 filed 12/1965 - C.S. File 54/16-23F

-----

Found - Stumps of all Orig. BTs. (Someone put these in)

- 12" Madrone, S.36°E., 63.1 ft. BT.
- 12" Fir, N.74°E., 22.1 ft. S25 BT
- 14" Fir, N.8°W., 61.5 ft. S26 BT.
- 36" I.Cedar, S.71°W., 94.7 ft. S35 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Stone - Jerry Layne - Oct. 1965 - C.S. File 54/16-2

-----

Found - Haines "T" iron & BT

- 15" D.Fir, N.74°E., 22.1 ft. scribe visible on partially healed scars.

We find badly burned & rotted stumps in location of orig. BTs, no scribe found.

Ken Hoffine, LS 2291 - For: Lone Rock Timber Co. - Jan. 1990 - M 109-56 & M 111-30 - C.S. File 63/106

-----

Found - 4x4" old burned, decayed cedar post lying next to point. Wilford Haines' 3/4" T-iron and identification button on top of bar bears West 8.45 ft. I find the following accessories:

- Orig. 6" D.Fir is now badly decayed, 20" root remains, bears S.40°E., 76.1 ft.

(Cont. next page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Orig. 36" D.Fir is now badly decayed, 40" root remains bears N.19°E., 104.5 ft.  
 Orig. 48" D.Fir is now badly decayed 50" 3 ft. tall snag remains, no marks visible, bears S.75°W., 115.1 ft.  
 Orig. 36" D.Fir is a burned decayed 34" IC stump, no marks visible bears N.5°W., 222.5 ft.  
 Set - 5/8" x 36" iron rod with alum. cap 0.7 ft. above ground.  
 10" Hemlock bears N.64°W. 46.0 ft. Wyeco tag and "W" nail in base, I scribe S26 BT and tag.  
 21" D.Fir high stump bears N.52°E., 15.0 ft. Well healed scribe and old BT tag.  
 29" D.Fir bears N.19°W., 64.0 ft. to alum. nail in mid-base. I drive a 6" iron spike into well healed face and tag tree.  
 10" Hemlock bears S.65°W. 52.3 ft. Weyco tag and "W" nail, I scribe S35 BT and tag tree.  
 25" WRC bears S.62°E. 61.3 ft. to alum nail @ DBH I drive 6" spike in face & scribe S36 BT & tag tree  
 Corner lies on the edge of large bench, steep to the south with timber to the Southeast only.

Donald Peel - For: Weyerhaeuser Co. - March 1993 - M 117-5  
 -----  
 At the NW sec. corner I found 2 monuments, one set by Wilford Haines in the early 1960's and another set in M 111-30 (Hoffine) in 1990. The M 111-30 corner was 8.37 ft. easterly of the Haines corner. In 1965 VR Tracy of the Douglas Co. Surveyors Office visited this corner and found all four of the Orig. BTs. Tracy also found four BTs that he stated were not set by Haines. Upon a review of Haines field book (Douglas Co. F.B. H-237) I found reference to these BTs, thus I assumed they were marked by Haines. As Tracy never set a new corner or marked an new BTs, I assumed he agreed with the corner position as established by Haines. At this time, I found:  
 The rotted remains of approx. 40" Fir stump (no visible scribing) N.9¼°W., 217.0 ft. (Rec. N.5°W., 221.1 ft.),  
 The rotted remains of a 36" Fir stump (no visible scribing) N.23 3/4°E., 106.6 ft. (Rec. N.19°E., 102.3')  
 The rotted remains of an approx. 48" Fir stump (no visible scribing) S.72 3/4°W., 109.4 ft. (Rec. S.75°W., 113.5')  
 I find no trace of the 6" Fir (when set in 1884) S.49½°E., 73.9 ft.  
 (Cont. next page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

These measurements were from the Haines corner. Had I been the first surveyor to determine this corner position, based on my analysis of what I believe to be the orig. BTs, I probably would have set the corner approx. 2 3/4 ft. South of the Haines corner. As the Haines corner has been in existence for approx. 30 years and as the original calls from the existing orig. BTs will not come together at a common point, the fixing of a corner position is judgmental so I accept the corner point as established by Haines. The position of the M 111-30 corner was determined on the basis of a found Cedar stump in the NW quadrant and a rotted Fir stump of approx. 40" to 48" in dia., in the SE quadrant. I believe the orig. surveyor knew the difference between a Cedar and a Fir and I find it hard to believe that the Fir stump in the SE quadrant, tied in M 111-30, was a 6" Fir in 1884.

- Found - Wilford Haines "T" bar with brass disk
- 21" Fir stump, N.67½°E., 22.0 ft. - closed face, GLO and USFS tags.
  - 25" Cedar, S.62 3/4°E., 68.9 ft. - visible scribe, USFS tag.
  - 14" Madrone, S.37¼°E., 63.2 ft. -opened face, no visible scribing.
  - 11" Hemlock, S.58½°W., 44.8 ft. - visible scribe, Weyco & USFS Tags.
  - 46" Cedar, S.72½°W., 93.6 ft. - Face partially chopped into previously.
  - 11" Hemlock N.56 3/4°W., 38.7 ft. - Visible scribe, Weyco & USFS tags.
  - 30" Fir N.9 3/4°W., 61.6 ft. - closed face, USFS tag

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2168, Surveyed May/Nov. 2007 - DCSO records Vol. 57 Page(s) 22590-1

The cor. of secs 25, 26, 35, & 36, perpetuated by Haines, in about 1960, accepted as a careful and faithful perpetuation of the orig. cor. position, monumented with a "T" shaped iron rod, 1" dia., firmly set, projecting 8" above ground, with 1" dia. brass disk mkd. WILFORD N HAINES 239 affixed to top, from which the remains of the orig. bearing trees

A decayed fir snag, size indeterminate, bears S.51¾°E., 82.6 ft., with no marks visible. (Record; S.49¼°E., 73.9 ft.)

A decayed fir stump, size indeterminate, bears S.72½°W., 107.8 ft., with no marks visible. (Record; S.75°W., 113.5 ft.)

continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A decayed fir stump, 34" dia., bears N.2¼°W., 231.3 ft., with no marks visible. (Record; N.5°W., 221.1 ft.) and BTs mkd. by person(s) unknown, reported by Haines  
A fir stump, 22" dia., bears N.67¾°E., 22.5 ft., with a healed blaze.  
A sawed madrone stump, 19" dia., bears S.37¼°E., 62.7 ft., with no marks visible.  
A cedar, 53" dia., bears S.72°W., 94.2 ft., with a healed blaze.  
A fir, 35" dia., bears N.9¾°W., 61.8 ft., with a healed blaze

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 25" in the ground, directly over the existing "T" shaped iron rod, with brass cap (properly) mkd.

T23S R4W  
S 26 | S 25  
S 35 | S 36  
2007

Bury a magnet in a white plastic case at the base of the stainless steel post.  
(NAD 1983 (CORS 96))

Latitude: 43°32'00.64"N. Longitude: 123°07'40.09"W

From this cor., a point established as the cor. of secs. 25, 26, 35, and 36 by Hoffine, in 1990, recorded in the Douglas County Surveyors Office, Map File Nos. 109-56 and 111-30, bears S.88¼°E., 8.45 ft., determined at record bearing and from bearing trees mkd. by Hoffine

A sawed cedar stump, 30" dia., bears S.62°E., 61.3 ft., with a healed blaze.

A hemlock, 15" dia., bears S.65°W., 52.3 ft., with a healed blaze.

A hemlock, 15" dia., bears N.64°W., 46.0 ft., with a healed blaze.

There is no remaining evidence of Hoffine's monument of record and this point is not accepted as the cor.