

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor. Secs 13, 14, 23, & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 6 Page(s) 2288-89)

Set post cor. of secs. 13, 14, 23, & 24 from which:
A Fir, 10" dia., bears N.31°E., 11 lks.
A Fir, 10" dia., bears S.26°W., 20 lks.
A Cedar, 20" dia., bears N.77°W., 42 lks.
A Fir, 80" dia., bears S.20°E., 66 lks.)

Fd. & used in Original GLO - William P. Wright, Deputy Surveyor, under Contract No. 514, dated Aug. 27, 1884 (DCSO records Vol. 6 Page(s) 2305)

Wilford Haines - June 1963 - C.S. File 51/247-5

Found - Mound of stone at corner.
Cedar BT (Orig.) N.77°W., 42 lks., down.
No other trees near old enough for OBTs.

Set - 1" x 36" T iron in mound of stone.

New BTs- 24" Fir, N.12°E., 37.6 ft.
20" Fir, S.58°W., 63.0 ft.
12" Fir, N.72½°W., 8.4 ft.
24" Fir, S.21°E., 27.9 ft.

BLM dependent resurvey by James E. Jelly, Cadastral Surveyor, under Group #733, surveyed Apr. 1971 (DCSO records Vol. 6 Page(s) 14538-39)

From the sec. cor., perpetuated and recorded by Haines in 1963 at which time evidence of the orig. NW BT was in existence, monumented with a 1" T iron, firmly set, projecting 8" above the ground.
from which BTs mkd. by Haines

- A Fir, 23" dia., bears N.12°E., 57½ lks., with healed blaze.
- A Fir, 26" dia., bears S.21°E., 42½ lks., with healed blaze.
- A Fir, 21" dia., bears S.58°W., 95½ lks., with healed blaze.
- A Fir, 13" dia., bears N.72½°W., 13 lks., with healed blaze.

At the corner point
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
(Cont. next page)

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor. Secs 13, 14, 23, & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>T23S R4W S 14 S 13 S 23 S 24 1971</p> <p>Reset T iron alongside the iron post.</p>
<p>Fd & used in BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41 Page(s) 16141)</p>
<p>BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #1083 - Surveyed Nov. 1981/April 1982 (DCSO records Vol. 46 Page(s) 17539-40)</p>
<p>Ken Hoffine - For: Juniper Properties Ltd. - Aug. 1994 - M 120-66.</p> <p style="text-align: center;">-----</p> <p><u>CONDITION REPORT ONLY.</u></p> <p>Found - BLM Brass cap flush to the ground. 22" D.Fir stump with tin cap bears S.58°W., 63.1 ft. bark has been removed, no visible face. 12" D.Fir stump with tin cap bears N.72½°W., 8.5 ft. bark has been removed, no face or tag visible. 25" D.Fir stump with tin cap bears S.21°E., 28.0 ft. bark has been removed, visible scribing, no tag. 21" D.Fir stump with tin cap bears N.12°E., 37.9 ft. bark has been removed except for the face which has bark scribing. 2" D.Fir bears N.63°W., 5.8 ft. no scribing, we tagged.</p> <p>Note - Corner lies in young re-prod with mature stand 150 ft. to the south.</p>
<p>BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2147, surveyed Aug/Nov. 2006 - (DCSO rec. Vol. 55 Page(s) 21411-12)</p> <p style="text-align: center;">-----</p> <p>The cor. of secs. 13, 14, 23, & 24, monumented with an iron post, 2½" dia., flush with the ground, with brass cap (properly) mkd. from which the remains of bearing trees mkd. by Haines, in 1963, reported by Jelley in 1981-82 A tin-capped, sawed fir stump, 22" dia., bears N.9½°E., 38.0 ft with scribe marks T23S R4W1 visible on the bark A sawed and decayed fir stump, 24" dia., bears S.17¼°E., 28.1 ft., with no marks visible. A tin-capped, sawed fir stump, 23" dia., bears S.55°W., 63.0 ft., with no marks visible. continued next page</p>

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor Secs 13, 14, 23, & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A tin-capped, sawed and decayed fir stump, 13" dia., bears N.74½°W., 8.6 ft., with no marks visible.
and new bearing trees
A fir, 7" dia., bears N. 12¾°E., 12.6 ft., mkd. T23S R4W S13 BT.
A fir, 10" dia., bears S.62¾°E., 5.8 ft., mkd. T23S R4W S24 BT.
A fir, 6" dia., bears S.33¾°W., 29.9 ft., mkd. T23S R4W S23 BT.
A fir, 10" dia. bears N.23°W. 7.4 ft. mkd. T23S R4W S14 BT
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2168, Surveyed May/Nov. 2007 - DCS0 records Vol. 57 Page(s) 22594-5

The cor. of secs. 13, 14, 23 and 24, monumented with an iron post, 2½" dia., flush with the ground, with brass cap (properly) mkd.
from which the remains of BTs mkd. by Haines, in 1963
A tin-capped, sawed fir stump, 22" dia., bears N.9½°E., 38.0 ft with scribe marks T23S R4W1 visible on the bark
A sawed and decayed fir stump, 24" dia., bears S.17¼°E., 28.1 ft., with no marks visible.
A tin-capped, sawed fir stump, 23" dia., bears S.55°W., 63.0 ft., with no marks visible.
A tin-capped, sawed and decayed fir stump, 13" dia., bears N.74¼°W., 8.6 ft., with no marks visible.
and bearing trees mkd. by Skeesick and Browning
A fir, 7" dia. bears N.12¾°E., 12.6 ft., with scribe marks T23S R4W S13 BT visible on a partially healed blaze
A fir, 10" dia., bears S.62¾°E., 5.8 ft., with scribe marks T23S R4W S24 BT on a partially healed blaze.
A fir, 6" dia., bears S.33¾°W., 29.9 ft. with scribe marks T23S R4W S23 BT visible on a partially healed blaze.
A fir, 10" dia., bears N.23°W., 7.4 ft., with scribe marks T23S R4W S14 BT visible on a partially healed blaze.