

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor Secs 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records Vol. 6 Page(s) 2289-90)

Set post for sec. cor. from which
A B.Oak, 18" dia., bears S.8°W., 455 lks.
A W.Oak, 24" dia., bears S.26°E., 617 lks.
A W.Oak, 24" dia., bears N.4°W., 960 lks.
A Fir, 74" dia., bears N.2½°E., 10 lks.

Oscar F. Thiel - Floyd Durgett - R. Nelson - 1940 - "Old"
Vol. 1 Renewed Corners Pg. 33 & C.S. File 16/55 & C.S. File
61/5-4 & 61/5-8

I establish this corner from the SE & SW bearing trees both
dead, cut in SW tree & found old marks. NE & NW trees gone.
Set - A Stone 24" x 16" x 12" in mound of stones, 12" in
ground marked X CS from which I mark:
A Fir, 10" dia., bears N.63°E., 30.7 ft. mkd: T23S R4W
Sec. 1 CS.
A Fir, 60" dia., bears N.80°W., 9.6 ft. mkd: T23S R4W
Sec. 2 CS.
A Fir, 20" dia., bears S.51°W., 42 ft. mkd: T23S R4W
Sec. 11 CS.
A Fir, 28" dia., bears S.66°E., 15.8 ft. mkd: T23S R4W
Sec. 12 CS.

Lester Calder - G. McChesney - For: Weyerhaeuser Timber Co. -
April 1960 - C.S. File 51/87-1 & 53/108-2

Found - Post gone
Orig. SW & NE BTs gone.
24" W.Oak, S.26°E., 617 lks., remains of Oak moved
by logging. OBT
24" W.Oak, N.4°W., 960 lks., remains of Oak moved
by logging. OBT
Stone with "X" on top and "CS" on South. Thiel 1940
10" Fir N.63°E., 30.7 ft. 12"x3' Fir stub - scribing
visible.
30" Fir N.80°W. 9.6 ft. 32" Fir - faces healed over.
20" Fir S.51°W. 42.0 ft. 22" Fir - faces healed over.
28" Fir S.66°E. 15.8 ft. 36" Fir - faces healed over
Referenced stone as follows with Plates and "W" nails only -
12" Fir, N.24°E., 39.5 ft.
32" Fir, S.69°E., 15.1 ft. CS BT
22" Fir, S.50°W., 41.5 ft. CS BT
36" Fir, N.79°W., 8.7 ft. CS BT

(Cont. next page)

1

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Stone - Jerry Layne - Nov. 1965 - C.S. File 54/16-38

Found - BTs as recorded by Weyerhaeuser in 1960.
32" D.Fir, S.69°E., 15.1 ft. to face, shows scars, alive.
22" D.Fir, alive, S.50°W., 41.5 ft., to face, shows scars, "W" nail - alive.
36" D.Fir, alive, N.79°W., 8.7 ft., to face, shows scars, "W" nail - alive. Wire fence attached to north side.
NE BT now shattered stump.
Set - Brass cap at cor. mkd:
 COUNTY SURVEYORS T23S R4W S 2 | S 1
 OFFICE 1965 S11 | S12
21" R.Cedar, N.55°E., 175 ft. (center) mkd: T23S R4W S1 CS BT.
Note - This corner lies 2.0 ft., S. of fence, bearing S.78°E.

Douglas Co. Surveyors Office - A. Victor Cangie - Mike Tompkins - Nov. 17, 1976 - C.S. File 56/26-15

Found - A 1"x30" BC and stone. No identifiable marks on stone. Cap is stamped 1965, Douglas County Surveyors Office. From which:
A 32" now 35" D.Fir, bears S.69°E., 15.1 ft. to face, alive & show scar.
A 22" now 35" D.Fir, bears S.50°W., 41.5 ft. to face, alive and shows scar.
A 36" Fir stump bears N.79°W., 8.7 ft. to face, shows good scar.
A 21" now 26" R.Cedar, bears N.55°E., 175.0 ft. to center. Tree is healthy and shows good scar.
New BT - A 21" D.Fir, bears N.26½°W., 78.5 ft. to center & mkd: "T23S R4W S2 CS BT" in a double blaze.
Note - Corner lies 2.0 ft. south of fence bearing S.78°E., we also stamp "CS 1976" on found brass cap.

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1955, surveyed 2000/2001. (DCS0 rec. Vol. 54 page(s) 20836-7)

The cor. of secs. 1, 2, 11, & 12, perpetuated from evidence no longer in existence by Theil, in 1940, further perpetuated by Calder, in 1960, further perpetuated by Tracy, in 1965, continued next page

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor Secs 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

further perpetuated by Cangie, in 1976, monumented with an iron pipe, 1½" dia., firmly set, projecting 15" above the ground, with brass cap (properly)mkd.,
from which the remains of bearing trees mkd. by Theil
A fir, 40" dia., bears S.67¼°E., 16.0 ft., with a healed double blaze.
A fir, 41" dia., bears S.52¼°W., 42.2 ft., with a healed double blaze.
A fir snag, 37" dia., bears N.76°W., 10.6 ft., with a healed double blaze.
and the remains of a bearing tree mkd. by Tracy
A sawed cedar stump, 25" dia., bears N.56°E., 174.8 ft., with no marks visible.
and the remains of a bearing tree mkd. by Cangie
A sawed and decayed fir stump, 12" dia., bears N.27°W., 79.5 ft., with scribe marks 23S R4W S2 CS visible on partially healed blaze.
and new bearing trees
A fir, 6" dia., bears N.59¼°E., 20.2 ft., mkd. X BT.
A fir, 11" dia. bears N.7½°W. 14.3 ft. mkd. T23S R4W S2 BT

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Corner is located South, 2.0 ft., of an unmaintained woven wire fence, fences extending east and west.