

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 36; & 1, T24-4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 6 Page(s) 2321)

Set a Yew post 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. mkd. ¼ S on N. face, from which
A Hemlock 16" dia., bears N.30°E., 15 lks. dist. mkd. ¼ S BT.
A Yew 8" dia., bears S.27°E., 11 lks. dist. mkd. ¼ S BT.
Cor. is on a hillside, sloping NW. 75 ft. below spring.

Marion D. Hale - Weyerhaeuser Co. - June 22, 1959 - C.S. File 53/108-12

Yew Post gone.
Found - 16" Hemlock, now a snag.
8" Yew, gone.
Set new Yew post, from which
22" Hemlock snag bears N.30°E., 9.9 ft.
Accessories added this date:
34" Fir stump N.9°E., 29.8 ft. "W" nail and plate.
42" Cedar S.50°W., 26.8 ft. "W" nail and plate.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Mike Stone - July 1963 - C.S. File 53/9-112

Found - 26" Hemlock stump, dead several years, N.30°E., 9.9 ft., scribing visible in partially opened scar "¼".
No trace of SE. BT, location falls in old cat road.
Set Brass cap at cor. mkd: County Surveyors Office
T23S R4W S 36
T24S S 1
1963
New BTs- 11" Yew N.29°E., 6.5 ft. mkd. ¼ S36 CS BT.
24" Red Cedar S.63°W., 36.6 ft. mkd. ¼ S1 CS BT.

Fd. OK, March 1993 by D. Peel - M 117-5