

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - William P. Wright, Deputy Surveyor, under Contract No. 514, dated Aug. 27, 1884 (DCSO records Vol. 6 Page(s) 2302)

Set post 4" dia., 4 ft. long, with marked stone 12" in ground for ¼ sec. cor. mkd: ¼ S on N face, from which
A Fir, 40" dia., bears N.8°W., 38 lks., mkd: ¼ S BT.
A Fir, 48" dia., bears S.50°E., 35 lks.

Fd. & used by GLO Retracement - Carl S. Nicklin, Deputy Surveyor, under Contract No. 664, dated May 23, 1896 (DCSO records Vol. 6 Page(s) 2328)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Stone - Jerry Layne - Oct. 1965 - C.S. File 54/16-3

Condition Report only
Found - Basalt stone 6"x6"x8", firmly set, we find no marks.
54" Fir stump S.50°E., 23.1 ft., no scribe found.
These stumps fit bearing & distance for orig. BTs, we find unrecorded BTs as follows:
12" R.Cedar S.70°E., 14.5 ft., scribe visible on almost completely healed scar.
14" Hemlock N.56°E., 7.0 ft., scribe visible on partially healed face.