

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T23-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors,
under Contract #31 dated April 7, 1853 (DCSO records Vol. 6
Page(s) 2341)

Set ¼ sec. post, from which
A Fir 16" dia., bears N.39°E., 51 lks.
A Fir 20" dia., bears S.46°W., 36 lks.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen,
Cadastral Surveyors, under Group #244, surveyed June
1943/October 1957 (DCSO records Vol. 30 Page(s) 12637-38)

Point for the ¼ sec. cor., at proportionate distance; there
is no remaining evidence of the original corner.
Set an iron post, 3 ft. long, 1" dia., 27" in the ground with
brass cap mkd. ¼
S 24 | S 19
1943

from which
A Fir 40" dia., bears S.33°E., 67 lks. dist., mkd. ¼ S19
BT.
A Fir 36" dia., bears N.70°W., 144 lks. dist., mkd. ¼ S24
BT.

Survey by Wilford N. Haines - For: Yoncalla Lumber Co. - Aug.
1961 - M 23-33

Found - GLO brass cap set in 1943.
40" Fir S.33°E., 67 lks, down.
36" Fir N.70°W., 144 lks., a stump.
New BTs -14" Fir N.70°E., 40.6 ft.
10" I.Cedar N.2°W., 49.2 ft.

Survey by Ken Hoffine - For: Lone Rock Timber Co. - June 1990
C.S. File 63/104-57

Found - Corner is a brass cap 0.5 ft. above ground. Corner
has been bent nearly 40° from plumb in a west
direction.
36" Fir stump bears N.70°W., 95.8 ft. scribing
visible.
1943 40" SE BT, is a blown down badly decayed tree.
New BTs -Put Lone Rock Timber location tag on a 11" D.Fir
bearing S.25°W., 6.0 ft.
Put Lone Rock Timber location tag on a 8" D.Fir
bearing S.22°E., 9.5 ft.

(Cont. Next Page)

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24 of T23-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Painted face and wrote BT on tree trunk of BTs with flourescent orange paint. Corner lies on steep West slope approx. 2½ chs. West of gravel road, 15-20 year old timber West and a clearcut to the East.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/August 22, 1995 - (DCSO records Vol. 51 Page(s) 19457)

The 1/4 sec. cor., monumented with an iron post, 1 in. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

1/4
S 24 | S 19
1943

from which the remains of bearing trees mkd. by Gould, Gawron, and Eggen

A sawed fir stump, 27 ins. diam., bears N. 72 3/4° E., 61 lks. dist., with healed blaze. (Rec. S. 33° E., 67 lks.)

A sawed fir stump, 38 ins. diam., bears N. 68½° W., 141 lks. dist., with healed blaze. (Rec. N.70 W., 144 lks.)

and new bearing trees

A fir, 10 ins. diam., bears S. 21 3/4° E., 14 lks. dist., mkd. 1/4 S19 BT.

A fir, 12 ins. diam., bears N. 66° W., 27 lks. dist., mkd. 1/4 S24 BT.

From this point, Bureau of Land Management Geodetic Control Station No. EC 41179, at latitude 43° 33' 31.936" N. and longitude 123° 23' 27.852" W. (NAD 1927), determined by the NAVSTAR Global Position System, bears N. 84° 31' 10" W., 185.892 chs. dist. (mean bearing and sea level distance), monumented with an aluminum cap set flush with the ground, mkd. EC 41179 GPS 1993 and a triangle.

DCSO-GIS Corner visitation - 1/31/2006 - Typed: 1/11/2011 - C.S. File 67/33-1

Monument - 2½" BC/IP. Comment - 2 live BTs

Fd. Ok by Ken Hoffine, 1/2006 - M149-61

continued next page

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T23-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2315, Surveyed May/June 2010 - DCSO records Vol. 57 Page(s) 22774

The ¼ sec. cor. of secs. 19 & 24, on the W. bdy. of the Tp., ...monumented with an iron post, 1" dia., firmly set, projecting 5" above the ground, with brass cap (properly) mkd from which the remains of bearing trees mkd. by Gould, Gawron, and Eggen, reported by Rogers, et al

A sawed fir stump, 27" dia., bears N.72¾°E., 40.3 ft., with scribe marks S 19 visible on a decayed open face. and bearing trees mkd. by Rogers, et al

A fir, 13" dia., bears S.21¾°E., 9.2 ft., with a healed blaze.

A fir, 16" dia., bears N.66°W., 17.8 ft., with a healed blaze.