

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7, 8, 17 and 18

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2378)

-
- Set post, cor. to secs. 7, 8, 17 and 18, from which
- A Fir 18" dia., bears N.8°W., 17 lks.
 - A Fir 12" dia., bears N.80½°E., 47 lks.
 - A Fir 8" dia., bears S.89°E., 59 lks.
 - A Fir 14" dia., bears S.59½°W., 20 lks.

Survey by Robert G. Dean - For: Harold Peterson - Feb. 1989 -C.S. File 63/67 and M 107-61

Set 3/4" x 36" Iron rebar stamped "LS 1808" on top in center of rotted 9" Yew fence corner.
Post hole 27 ft. N. of creek and 75 ft. W. of creek.

Douglas Co. Surveyors Office - Randall Smith; Stephen Flause - April 13, 1989 - C.S. File 62/63-4

Found - A 3/4" Iron rod stamped "LS 1808" protrudes 3" out of an 8" dia., wood post. I.R. is in a 2 ft. dia. 1 ft. deep dug out hole. (Set by R. Dean in survey M 107-61)

Found possible remains of three original bearing trees; no blazes, scribe or axe marks found. (No evidence of orig. NE BT found.)

- 18" now depression in ground, dug up remnants of badly deteriorated burnt trunk and roots of indeterminable size D.Fir bears N.8°W., 11.2 ft. (agrees w/rec.)
- 8" now depression in ground, dug up remnants of badly deteriorated burnt trunk of indeterminable size D.Fir bears S.89°E., 38.9 ft. (agrees w/rec.)
- 14" now completely deteriorated tree, dug up small pieces of burnt wood, bears S.59½°W., 13.2 ft. (agrees w/rec.)

3/4" Iron rod set by Robert Dean perpetuated by BTs described below:

- 7" D.Fir, double blazed and scribed "T23S R5W CS BT" bears N.80½°E., 6.7 ft.
- 8" D.Fir, double blazed and scribed "T23S R5W S17 CS BT" bears S.21°E., 7.4 ft.
- 6" D.Fir double blazed and scribed "T23S R5W S18 CS BT" bears S.23½°W., 23.5 ft.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. cor. for 7, 8, 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

7" Madrone bark scribed "T23S R5W S7 CS BT" bears N.30°W., 20.4 ft.
 Corner lies at cut line and old fence corner. Calls of a stream South and East fits well with position of corner determined by Dean. Stream position to the East is a little long, stream looks to have moved East.

Fd. OK, Dec.1993, D. Baker, M 118-43

BLM dependent resurvey by Wayne Rogers & Bryan Seibold, Cadastral Surveyors, under Group #1832 surveyed July - Oct. 1997 - (DCSO recs. Vol. 53 Pg(s) 20279-80)

From the cor. of secs. 7, 8, 17 & 18, perpetuated by Dean, in 1989, from original topography calls and a fence corner, and is accepted as the best available evidence of the original corner position; further perpetuated by Smith & Flause, Deputy County Surveyors, in 1989, monumented with an iron rod, 3/4" diam., firmly set flush with the ground, from which bearing trees mkd. by Smith and Flause:

- A fir, 9" diam., bears N.81¼°E., 11½ lks., with healed double blaze.
- A fir, 10" diam., bears S.22¼°E., 11½ lks., with healed double blaze.
- A fir, 7" diam., bears S.23°W., 35½ lks., with healed double blaze.
- A madrone, 7" diam., bears N.29 3/4°W., 33½ lks., with scribe marks T23S R5W S7 CS BT visible on the bark.

At the corner point
 Set a stainless steel post, 28" long, 2½" diam., 26" in the ground, directly over the iron rod, with brass cap mkd.

T 23 S R 5 W

S 7	S 8
S 18	S 17

1997

Deposit a magnet in a white plastic case at the base of the stainless steel post.
 The corner is located at an old fence corner with remnants of old fences extending N. and W., and N., 0.42 chs. from a creek, 2 lks. wide, course N.50°E. and W., 1.23 chs. from the same creek, 2 lks wide, course N.35°E.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
 - 5/29/2007 - C.S. File 67/21-54

Fd. ok - Madrone in NW quadrant now snag, other 1989 renewal BTs fd as per record.