

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2380)

-----

Set post, cor. to secs. 5, 6, 7 and 8, from which

- A W.Oak 13" dia., bears S.57½°E., 191 lks.
- A W.Oak 18" dia., bears S.8°W., 691 lks.
- A Y.Oak 12" dia., bears N.57°E., 246 lks.
- An Ash 10" dia., bears N.73½°W., 764 lks.

Douglas Co. Surveyors Office, James Byron, Deputy - May 7, 1956 - C.S. File 47/80

-----

Found - Orig. SE BT down and badly burned. Near base found what appeared to be bottom of old blaze. No evidence of any other old Oak near.

Found base of old Oak stump for NE BT.  
I used these BTs to set corner as they check for bearings, distance and size.

Set Brass cap at cor. mkd: County Surveyors Office

T	23	S	R	5	W
	S	6		S	5
	S	7		S	8
				1956	

Blazed and scribed:

- 18" R.Fir S.11°E., 46.0 ft. S8 T23S R5W CS BT.
- 18" W.Oak S.11½°W., 79.0 ft. S7 T23S R5W CS BT.
- 14" B.Oak N.25°E., 72.9 ft. S5 CS BT.

No other trees near.

Fd. OK, DCSO, V. Tracy, Sept. 1969, C.S. File 54/16-57

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed 1982 (DCSO records Vol. 46 Page(s) 17672)

-----

The sec. cor., perpetuated and recorded by Byron in 1956, from original evidence no longer in existence, monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground with 1956 brass cap.

from which the remains of bearing trees mkd. by Bryon:

- A B.Oak 28" dia., bears N.24¼°E., 109 lks. dist., with healed blaze.
- A Fir stump 30" dia., bears S.12½°E., 68 lks. dist., with healed blaze.
- An Oak 25" dia., bears S.10½°W., 119 lks. dist., with healed blaze.

(Cont. Next Page)

