

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2381)

Set ¼ sec. post, from which
A Y.Oak 16" dia., bears N.31½°E., 185 lks.
A Y.Oak 36" dia., bears N.13¼°W., 141 lks.

O.F. Thiel - For: Miller's - Nov. 1930 (recorded 8/31/1998) - F.B. 116 Pg. 28

Old stake in place, both old trees gone, marked BT:
B.Oak 40", S.86°W., 16½ lks.

O.F. Thiel - For: Sherman Bros - Aug. 1933 - C.S. 61/5-10

New B.Oak post, old stake decayed. Marked
A B.Oak 36" S.85°W., 18 ft.
16" Fir S.87°E., 14 ft.

Survey by Wilford N. Haines - For: Yoncalla Lumber Co. - June 1960 - M 19-6

Set 1" x 1" x 36" T iron.
Scribed -16" Fir S.50°W., 9.8 ft.
Found - 16" Fir S.85°E., 10.0 ft. scribed ¼ S BT, when 10".

Douglas Co. Surveyors Office - Gary Langlitz, Deputy - P. Earle & C. Goodwin, Crew - Feb. 14, 1974 - C.S. File 56/43-16

Found - 1" x 1" T-Iron with copper washer attached mkd. Wilford N. Haines 239 Survey Point Drain, Oregon

From which:
16" D.Fir now down, bears S.50°W., 9.8 ft. with blaze and copper washer visible on lower side.
16" D.Fir now down, bears S.85°E., 10.0 ft. scribing visible in previously opened blaze.

Set Brass cap alongside T-Iron mkd:
County Surveyors Office
T 23 S R 5 W

¼
S 6 | S 5
1974

New BTs -8" D.Fir bears N.31°W., 74.6 ft. scribed ¼ S6 CS BT.
14" Red Cedar bears S.45°W., 55.3 ft. scribed ¼ S6 CS BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed 1982 (DCSO records Vol. 46 Page(s) 17673-74)

Point for the 1/4 sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original cor. Set an alum. post, 28" long, 2 1/2" dia., 24" in the ground, with alum. cap mkd:

T 23 S R 5 W
1/4
S 6 | S 5
1982

from which

- A Fir 15" dia., bears S.14°E., 44 lks. dist., mkd. 1/4 S5 BT.
- A Fir 6" dia., bears N.56 1/2°W., 20 lks. dist., mkd. 1/4 S6 BT.

From this point, a point established and recorded by Haines in 1960, and perpetuated and recorded by Langlitz in 1974, bears N.30°30'E., 0.175 chs. dist., monumented with a "T" shaped iron rod, 1" dia., firmly set, projecting 6" above ground, with steel washer mkd. Wilford N. Haines 239 Survey Point Drain Oregon, with an iron pipe alongside 1 1/2" dia., firmly set, projecting 10" above ground, with brass cap sawed off, from which the remains of a bearing tree recorded by Haines

- A root hole bears S.85°E., 15 lks. dist., with a down Fir alongside 18" dia., with fragmentary scribe marks visible on opened blaze.
- and the remains of a bearing tree mkd. by Haines
- A root hole bears S.50°W., 15 lks. dist., with a down Fir alongside 18" dia., with healed blaze.
- and bearing trees mkd. by Langlitz
- A Cedar 19" dia., bears S.45°W., 84 lks. dist., with healed blaze.
- A Fir 17" dia., bears N.31°W., 114 lks. dist., with healed blaze.

The corner is located on spur, slopes N.50°W.