

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec Cor for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2369)

Set post, cor. to secs. 16, 17, 20 and 21, from which
A Fir 18" dia., bears S.55°W., 3 lks.
A Fir 30" dia., bears N.40°W., 18 lks.
A Fir 20" dia., bears S.82½°E., 20 lks.
A Fir 28" dia., bears N.50°E., 58 lks.

Survey by Wilford Haines - For: Western Land & Timber Co. - Feb. 1959 - M 14-8

Found old bearing trees:
30" Fir N.40°W., 18 lks. (stump)
18" Fir S.55°W., 3 lks.
28" Fir N.50°E., 58 lks. (stump)
20" Fir S.82½°E., 20 lks.
Set 1" x 1" x 36" T Iron with brass cap inscribed "Survey Point Wilford N. Haines #239"

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Oct. 30, 1959 - C.S. 49/42-13

Found - Haines T Iron at corner.
Orig. 28" now 36" Fir stump, shows good scribing "T23S", N.50°E., 38.3 ft.
Orig. 20" now 40" Fir snag S.82½°E., 13.2 ft., shows good scribing "T23S R5W S21 BT"
Orig. 30" now rotted Fir stump, N.40°W., 11.9 ft.
Orig. 18" now 40" Fir, shows old scars, I do not open., S.55°W., 2.0 ft.
New BTs -7" R.Fir bears N.61½°E., 37.9 ft. scribed S16 CSBT
8" R.Fir bears N.84½°W., 89.6 ft. scribed S17 T23S R5W CS BT.
8" W.Oak bears S.12°E., 22.2 ft. scribed S21 T23S R5W CS BT.

Douglas Co. Surveyors Office - Milo Godfrey and crew - Nov. 27, 1964 - C.S. File 49/42-66

Found - "T" Iron with cap at corner.
Accessories as per 1959, except 40" Fir S.55°W., 2.0 ft. has blown down. Corner monument not disturbed.
Fir snag S.82½°E., 13.2 ft. scribing still plain.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 16, 17, 20 and 21

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

7" D.Fir N.61½°E., 37.9 ft. very good scar, Tree in good condition.
 8" D.Fir N.84½°W., 89.6 ft. very good scar, tree in good condition.
 8" W.Oak S.12°E., 22.2 ft. scribing still visible, tree in good condition.
 New BT - 13" B.Oak S.84°W., 26.6 ft. mkd: T23S R5W S20 CS BT

Fd. OK, Sept. 1969, DCSO, C.S. File 54/16-57

BLM dependent resurvey by Wayne Rogers & Bryan Seibold, Cadastral Surveyors, under Group #1832 surveyed July - Oct. 1997 - (DCSO recs. Vol. 53 Pg(s) 20277-8)

 The cor. of secs. 16, 17, 20 & 21, perpetuated by Haines, , in 1959, further perpetuated by Byron, in 1959, and by Godfrey, in 1964, monumented with a "T" iron, firmly set, projecting 18" above ground, with brass washer mkd. WILFORD N HAINES 239 SURVEY POINT DRAIN ORE., from which the remains of an original bearing tree:
 A decayed fir stump, size indeterminate, bears S.82½°E., 20 lks., with fragmentary scribe marks visible on fallen trunk, alongside.
 and bearing trees mkd. by Byron
 A fir, 16" diam., bears N.60 3/4°E., 58 lks., with healed double blaze.
 An oak, 10" diam., bears S.11½°E., 32½ lks., with healed double blaze.
 A fir, 28" diam., bears N.84°W., 136 lks., with healed double blaze.
 At the corner point
 Set a stainless steel post, 28" long, 2½" diam., 27" in the ground, directly over the "T" iron, with brass cap mkd.

T 23 S	R 5 W
S 17	S 16
S 20	S 21

1997

 from which a new bearing tree
 A fir, 8" diam., bears S.77¼°W., 41 lks., mkd. T23S R5W S20 BT.
 Deposit a magnet in a white plastic case at the base of the stainless steel post.
 The corner is located S., 0.08 chs. from a fence corner, with woven wire fences extending E. and S., and is set in the N. and S. portion of the fence.

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

DCS0-GIS Corner visitation - 1/25/2006 - Typed: 1/21/2011 -
C.S. File 67/33-1

Monument - 2½" SSP/BC Comment - 2 Live BTs, 2 stumps