

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2371)

Set ¼ sec. post, from which
A Y.Oak 28" dia., bears N.46°E., 61 lks.
A Y.Oak 36" dia., bears N.80°W., 113 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Nov. 1959 - C.S. File 49/42-15

Found - Orig. 28" now 42" B.Oak N.46°E., 40.3 ft. Opened years ago, upper face rotted and gone. I do not open lower scar. By extending my arm through upper opening, I am able to trace the reverse scribing "BT"

No trace of orig. NW BT found.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 5 W
¼ S 8 | S 9
1959

New BTs -20" W.Oak bears N.49°E., 46.8 ft. scribed ¼ S9 CSBT
15" R.Fir bears N.68½°E., 49.6 ft. scribed ¼ S9 CSBT
No trees near to West.

Cor. lies 2 ft. S. of fence cor., fences running N'ly & E'ly.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 11/14/2006 - C.S. File 67/14-44

Found - 2½" BC (properly mkd) on 1¼" iron pipe, firmly set projects 15" above ground.

20" now 20" 2 ft. tall W.Oak stump, rotted blaze bears N.49°E., 46/8 ft. (agrees w/rec) 1959

15" now 23"x1½ ft. tall D.fir stump, evid. of healed blaze, rotted center, bears N.68½°E., 49.6 ft. (agrees w/rec) 1959

Orig 28" now fractured remains of rotted B.Oak stump position checks ok (rec. N.46°E., 40.3 ft.) OBT

New - 14" dia., B.Oak, double blazed & scribed "¼ S9 CS BT" bears N.48¾°E., 39.0 ft.

11" dia., D.Fir, double blazed & scribed "¼ S8 CS BT" bears N.11½°W., 37.8 ft.

8" dia., D.Fir, double blazed & scribed "¼ S8 CS BT" bears S.49½°W., 12.0 ft.

16" dia., D.Fir, double blazed & scribed "¼ S9 CS BT" bears S.38°E., 25.0 ft.

Note - Lies 2 ft. ± South of well maintained fence cor. with fences extending N & E. Dec. 16½°E.