

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2371)

Set post, cor. to secs. 4, 5, 8 and 9, from which

- A Y.Oak 40" dia., bears S.11°W., 1175 lks.
- A Y.Oak 12" dia., bears S.10½°E., 1095 lks.
- A W.Oak 8" dia., bears N.71¼°E., 813 lks.
- A W.Oak 12" dia., bears N.89°W., 964 lks.

Douglas Co. Surveyors Office - Vernon Tracy, J. Heritage, V. Perron, crew - Sept. 1969 - C.S. File 54/16-55

Found - Unrecorded and unmarked stone at corner point by old Oak fence post. Fences mostly gone.

Orig. 12" now 48" W.Oak, alive, N.89°W., 636.2 ft., previously opened, rotted out, open higher and find reverse scribe.

No trace other orig. BTs due to cultivation many years ago.

Set Brass cap at cor. mkd: County Surveyors Office

T	23	S	R	5	W
	S	5		S	4
	S	8		S	9
					1969

New BTs -20" B.Oak S.43°W., 277.4 ft. mkd. T23S R5W S8 CSBT
 20" W.Oak S.84°E., 271.3 ft. mkd. T23S R5W S9 CSBT
 No other trees close - this corner lies in field.

Fd. OK, Sept. 1993, M 119-5

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 4/12/2006 - C.S. File 67/14-10

Found - 2½" dia., brass cap on 1¼: O.D. IP out of ground & wired vertical to a cedar fence post 3 ft. tall. Unmarked stone meas. approx. 15X6X2" fd. loose on top of ground between fence post & BC/IP.

20" now 34" dia., W.Oak, fully healed single blaze visible bears S.84°E., 271.3 ft. (agrees w/rec.) 1969 BT

Orig. 12" now a burnt rotten stump still in position no markings visible bears N.89°W., 636.2 ft. (agrees w/rec) OBT

20" B.Oak now a sawn Oak stump 32" dia., x 18" tall evidence of lower healed blaze bears S.43°W., 277.4 ft. (agrees w/rec.) 1969 BT

continued next page

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set - BC/IP was reset flush with ground using rec. information from the remaining 1969 BT & the 2 stumps. Stone was buried upright, flush w/ground on East edge added the words "RESET 2006" to BC. (In digging the hole to reset BC/IP we found remnants of the Oak fence post called out in the 1969 renewal.)
45" dia., B.Oak, double blazed & scribed "T23S R5W S5 CS BT" bears West, 564.9 ft.
19" dia., D.Fir double blazed & scribed "T23S R5W S8 CS BT" bears S.59½°W., 345.9 ft.
9" dia., madrone double blazed & scribed "T23S R5W S4 CS BT" bears N.81¼°E., 436.9 ft.
Note - Corner lies in cleared pasture land rolling terrain, 8" southerly of 3 ft. tall cedar fence post.

Fd. BC - 8" northerly of fence post. by D. Edwards - 7/2013 - M165-45 A&B