TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2363)

Set ¼ sec. post, from which
An Ash 16" dia.,bears S.3°W., 654 lks.
An Ash 10" dia., bears S.19°E., 680 lks.

Survey by Glenn Baughman - July 1971 - RM 2-29

Set by proportionate measurement.
Set 1" x 30" I.Pipe with brass cap.
Marked - 6" Plum tree, S.76°E., 76.3 ft.
Set - 5/8" I.Rod for witness corner, N.76°W., 14.7 ft.

BLM dependent resurvey by Wayne Rogers & Bryan Seibold, Cadastral Surveyors, under Group #1832 surveyed July - Oct. 1997 - (DCSO recs. Vol. 53 Pg(s) 20272)

Point for the ¼ sec. cor. of secs. 21 & 22, at proportionate distance, there is no remaining evidence of the original corner.
Set a stainless steel post, 28" long, 2½" diam., 28" in the ground, with brass cap mkd. T 23 S R 5 W
1/4
S 21 S 22
1997
from which
The most westerly trunk of a double trunk ash, 10" diam., bears S.49½°E., 231 lks., mkd. ¼ S22 BT.
An ash, 10" diam. bears S.26 3/4°W. 216 lks. mkd. ¼ S21 BT
Deposit a magnet in a white plastic case at the base of the stainless steel post and drive a metal fence post alongside.
The corner is located in a field.
From this point, a point erroneously reestablished as the ¼ sec. cor. of secs. 21 &22, by proportionate measurement by Baughman, in 1971, bears S.22°40'07"E., 0.657 chs. monumented with an iron post, 1½" diam., firmly set, projecting 16" above ground, with brass cap mkd. T23S R5W ¼ 21 22 1971 OLS 536, from which the remains of a bearing tree mkd. by Baughman:
A plum, 7" diam., bears S.81°E., 115 lks., with no marks visible on partially decayed double blaze.
This point was rejected due to erroneous position and improper control and was not used in this survey.