

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2359)

Set ¼ sec. post, from which
A W.Oak 10" dia., bears N.22°W., 678 lks.
A W.Oak 20" dia., bears N.1½°E., 683 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Jan. 1960 - C.S. File 49/42-44

Found - Orig. 10" now 36" W.Oak N.22°W., 447.5 ft. I open and find good scribing "¼S"
Orig. 20" now 44" W.Oak N.1½°E., 450.3 ft. Shows good scars, I do not open.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 5 W
¼ S10 | S11
1960

New BTs -10" R.Fir bears S.26½°E., 111.0 ft. scribed ¼ S11 CS BT.
6" R.Fir bears S.11°W., 198.4 ft. scribed ¼ S10 CSBT

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Jan. 5, 1993 - C.S. File 64/39-4

Found - Flanges of I.P. 18" below ground. I.P. and BC found by County Engineering Dept., out of ground near corner.

10" now 20" dia., 2 ft. high rotted Oak stump with a scribe mark visible "S", bears N.22°W., 448.4 ft. (Rec. N.22°W., 447.5 ft., dist. possible face measurement) Orig. BT.

20" now 38" dia., 3 ft. high rotted Oak stump. We opened, no scribing found, bears N.1°E., 448.3 ft. (Rec. N.1½°E., 450.8 ft.) Stump is tilted toward corner. Orig. BT.

6" now 20" dia. 1 ft. high rotted D.Fir stump. We opened lower blaze, scribe mark found "T", bears S.11°W., 198.4 ft. Agrees w/record.

20" now 26" dia. 1 ft. high rotted D.Fir stump, no blazes or scribing visible, bears S.26½°E., 111.0 ft. Agrees w/rec.

Set 1½" dia. x 32" long Iron pipe with brass cap in middle of found flanges. BC/IP protrudes 2" above ground. Flanges left under BC/IP. Brass cap mkd: "Douglas County Surveyors Office T23S R5W ¼ S10 | S11 1993".

(Cont. Next Page)

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

New Accessories:
5/8" x 30" long Iron rod with DCSO alum. cap stamped "B01" is set near center of BT stump from 1960. I.R. bears S.26 3/4°E., 110.6 ft.
5/8" x 30" long Iron rod with DCSO alum. cap stamped "B02" is set near center of BT stump from 1960. I.R. bears S.10 3/4°W., 198.4 ft.
26" dia. D.Fir double blazed and scribed "¼ S11 CS BT" bears N.1½°E., 264.1 ft.
11" dia. W.Oak double blazed and scribed "¼ S10 CS BT" bears N.34°W., 311.4 ft.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 2/28/2007 - C.S. File 67/21-17

Found - 2½" dia., brass cap properly mkd on 1¼" O.D. iron pipe projects 4" above ground, firmly set.
26" now 30" dia., Fir, fully healed double blaze, top now dead, bears N.1½°E., 264.1 ft. (agrees w/rec) 1993 BT
11" now 15" dia., W.Oak, fully healed double blaze, bears N.34°W., 311.4 ft. (agrees w/rec) 1993 BT
5/8" iron rod w/alum cap stamped "B 0 1" in rotten stump bears S.26¾°E., 110.6 ft. (agrees w/rec) 1993 accessory
5/8" iron rod "B 0 2" is fd on top of ground loose (Rec. S.10¾°W., 198.4 ft.)
No rotten stumps from previous renewal looked for.
New - 6" dia., D.Fir, double blazed & scribed "X" on high blaze & "CS BT" bears S.53½°W., 219.0 ft.
Note - Lies in open rolling hillside pasture.
Compass decl. 16¼°E.

G. Marcus Brittain - For: CMS Sheep Co. Inc./Scott Sublette - 11/2010 - 2010-0042

Fd 2½" brass cap mon. on open hillside per record.
Fd 6" D.Fir witness & 30" D.Fir witness per record, other accessories not field verified at this time.

Fd. BC as per DCSO 1993 ren. 5/2013, Todd Catterson; M165-19
Fd. as per record 4/2024 - D. Edwards - M183-55