

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18; & 13 of T23-7

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 6 Page(s) 2392)

-----  
Set Fir post for ¼ sec. cor., from which  
A Cedar 24" dia., bears N.40°E., 14 lks.  
A Cedar 14" dia., bears S.85°W., 5 lks.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12654)

-----  
The ¼ sec. cor., determined from the original bearing trees:  
A Cedar 30" dia., bears N.40°E., 5 lks., with healed blaze  
A Cedar 22" dia., bears S.85°W., 14 lks. dist., with marks  
BT on exposed face.

At the corner point  
Set an iron post, 3 ft. long, 2" dia., 30" in the ground,  
with brass cap mkd:  
T23S  
¼  
R7W|R6W  
S13|S18  
1957

from which  
A Fir 12" dia., bears S.39°E., 51 lks., mkd. ¼ S18 BT.  
A Fir 20" dia., bears S.39½°W., 43 lks., mkd. ¼ S13 BT.

David Edwards - Oct. 2011 - C.S. File 65/72-34

-----  
Found - 1957 BLM brass cap projecting 2" above ground. The cap is oriented 180° from normal.  
20" Fir capped stump bears S.39½°W., 28.4 ft. Scribing visible.  
Fir to SE completely missing.  
North-South fence around BLM reprod. is 6' West.  
New BTs- An 11" dia. Fir scribed "¼ S18 BT" bears N.7°E., 38.2 ft.  
An 8" dia. Fir scribed "¼ S13 BT" bears N.87°W., 15.2 ft.  
Set a 6 ft steel post 2 ft to the North.