

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2429)

-
- Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 28, 29, 32 and 33, mkd. T23S S28 on NE.; R6W S33 on SE.; S32 on SW.; and S29 on NW. faces with 1 notch on S. and 4 notches on E. edges, from which
- A Fir 30" dia., bears N.65°E., 15 lks. dist. mkd. T23S R6W S28 BT.
 - A Fir 24" dia., bears S.45°E., 100 lks. dist. mkd. T23S R6W S33 BT.
 - A Fir 48" dia., bears S.51°W., 13 lks. dist. mkd. T23S R6W S32 BT.
 - A Fir 24" dia., bears N.76°W., 45 lks. dist. mkd. T23S R6W S29 BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12690-91)

-
- The Sec. cor., determined at record distance from three of the original bearing trees:
- A Fir 47" dia., bears N.19¼°E., 23 lks. dist. mkd. BT. I remark alongside T23S R6W S28 BT. (Rec. bearing and dist. N.65°E., 15 lks.)
 - A Fir 45" dia., bears S.38°E., 100 lks. dist. with a healed blaze. I remark alongside old blaze T23S R6W S33 BT. (Rec. bearing S.45°E.)
 - A Fir 55" dia., bears S.48°W., 13 lks. dist. mkd. T23S R6W S32 BT. (Rec. bearing S.51°W.)
 - A Fir 45" dia., bears N.11 3/4°W., 45 lks. dist. mkd. with a healed blaze. I remarked alongside old blaze T23S R6W S29 BT. (Rec. bearing N.76°W.)

At the corner point
Set an iron post, 30" long, 2" dia., 20" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

T23SR6W
S29|S28
S32|S33
1957

Fd. and used in BLM resurvey by Brooks, Contract #244, surveyed April/May 1964 (DCSO records, Vol. 32 Page 13502)

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19493)

The cor. of secs. 28, 29, 32, and 33, monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T23S R6W
S29 | S28
S32 | S33
1957

from which the remains of the original bearing trees remarked by Gould, Gawron, and Eggen

A fir, 55 ins. diam., bears N. 19¼° E., 23 lks. dist., with partially healed blaze.

A fir, 33 ins. diam., bears S. 38° E., 100 lks. dist., with healed double blaze.

A fir, 52 ins. diam., bears S. 48° W., 13 lks. dist., with scribe marks T23 R6W S32 visible on bark blaze.

A fir snag, 44 ins. diam., bears N. 11 3/4° W., 45 lks. dist., with healed blaze.

and a new bearing tree

A hemlock, 4 ins. diam., bears N. 38° W., 16½ lks. dist., mkd. X BT.

Fd. BC & 5 BTs by Rob Ward, 6/2010 - C.S. File 65/69-29