

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2432-33)

Set Fir post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on W. face, from which
A Fir 30" dia., bears N.21°E., 62 lks. dist. mkd. ¼ S BT.
A Fir 6" dia., bears S.29°W., 53 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12694-95)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 20" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:
T23SR6W
¼
S20 S21
1957

from which
A Fir 18" dia., bears N.42°E., 51 lks. dist. mkd. ¼ S21 BT
A Fir 18" dia., bears N.50½°W., 41 lks. dist. mkd. ¼ S20 BT.

Cor. Fd. and used in BLM resurvey by Jelley, Rogers, and Bishop, Contract #1098, surveyed June 1982/Nov. 1983 (DCSO records, Vol. 46 Page 17733)

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19498)

Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.
T23S R6W
¼
S20 S21
1994

from which bearing trees mkd. by Gould, Gawron, and Eggen
(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 18 ins. diam., bears S. 85½° W., 89 lks. dist., with healed blaze.

A fir, 26 ins. diam., bears N. 79° W., 26 lks. dist., with healed blaze. I remark X at breast height and BT at the base.

and a new bearing tree

A fir, 18 ins. diam., bears S. 87° E., 27 lks. dist., mkd. ¼ S21 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

The corner is located at the toe of a steep NW. slope and on the E. edge of a flat bench.

From this point, the ¼ sec. cor. of secs. 20 and 21, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears S. 61° 03' 00" W., 0.667 chs. dist.; monumented with an iron post, 2 ins. diam., firmly set, projecting 8 ins. above the ground, in a collar of stone, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.