

PRIMARY CORNER DESCRIPTION Standard cor. for Secs. 4 & 5 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1428)

-----  
Set standard cor. to secs. 4 and 5, from which  
A Fir 18" dia., bears S.5°E., 57 lks. dist.  
A Fir 12" dia., bears S.58°W., 55 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Special Instructions dated Oct. 27, 1897 (DCSO records Vol. 4 Page(s) 1474)

-----  
I make diligent search for the standard cor. of secs. 4 and 5, but can find no evidence of same.  
Set a sandstone, 14x12x8 ins., 9" in the ground, for standard cor., mkd. S C on S. with 2 grooves on W. and 4 grooves on E. faces; from which  
A dead Fir 36" dia., bears S.82°E., 159 lks. dist., mkd. T23S R6W S4 BT.  
A dead Fir 30" dia., bears S.6½°W., 180 lks. dist., mkd. T23S R6W S5 BT.  
This cor. is in the bottom of ravine, course SW., 350 ft. below top of spur last noted.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12629-30)

-----  
The standard cor. of secs. 4 and 5, monumented with a sandstone, 14x12x8 ins., firmly set, with 2 grooves on W. and 4 grooves on E. faces, SC on S. face, from which the remains of the original bearing trees:

A stump hole bears S.82°E., 159 lks.  
A stump, burned, bears S.6½°W., 180 lks.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 24" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

T22SR6W  
S 33  
S 5\*S 4  
T23SR6W  
S C  
1955

from which

A Fir 18" dia., bears S.22½°E., 44 lks. dist., mkd. T23S R6W S4 SC BT.  
A Fir 14" dia., bears S.33½°W., 72 lks. dist., mkd. T23S R6W S5 SC BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Standard cor. for secs. 4 and 5 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Reset corner stone alongside the iron post, properly oriented.  
This corner falls in the bed of a ravine, drains SW.

Ken Hoffine - Dec. 1995 - C.S. 65/2-1

-----

Mon. FD.- BLM Brass Cap set in 1957 in good condition.  
Bt's Fd.- 24" D.Fir, bears S.33½°W., 46.4', we tag tree.  
well healed face.  
30" D.Fir, bears S.41°E., 13.2', tree marked w/  
an "H" & "N" P.K. nail face pointing toward  
center.  
18" D.Fir, blow down S.22½°E., no marks visible  
corner lies in mound of stone 1' above ground at head of  
swale on south facing slope.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor  
Under Group No. 2653, Surveyed June/July 2012 - DCSO records  
Vol. 58 Page(s) 22983

-----

The standard cor. of secs. 4 and 5, on the N. bdy. of T.23S.,  
R.6W., monumented with an iron post, 2" dia., firmly set,  
projecting 14" above ground, in a mound of stone, 2 ft. dia.,  
1 ft. high, with brass cap (properly) mkd.  
from which the remains of an original bearing tree  
A burnt, decayed fir stump, size indeterminate, bears  
S.8¼°W., 118.8 ft., with no marks visible. (Record,  
S.6½°W.)  
and remains of bearing trees mkd. by Gould, Gawron, and Eggen  
A decayed fir stump, size indeterminate, bears S.18¼°E.,  
29.0 ft., with no marks visible. (Record, S.22½°E.)  
A fir, 26" dia., bears S.33½°W., 47.5 ft., with a healed  
blaze.  
and a new bearing tree  
A fir, 6" dia., bears S.31¼°E., 37.0 ft., mkd. T23S R6W S4  
SC BT.  
Corner is located in the bottom of a draw, drains S.50°W.