

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2436)

-----  
Set Cedar post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which  
A Cedar 36" dia., bears N.24°W., 7 lks. dist. mkd. 1/4 S BT  
A Cedar 24" dia., bears S.11°E., 14 lks. dist. mkd. 1/4 S BT

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12698)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30" long, 2" dia., 26" in the ground, with brass cap mkd:

T23SR6W  
1/4 S 9  
S 16  
1957

from which

A Fir 14" dia., bears N.77 1/2°E., 15 lks. dist. mkd. 1/4 S9 BT  
A Fir 14" dia., bears S.12 1/2°W., 49 lks. dist. mkd. 1/4 S16 BT.

Wilford N. Haines and Leo J. Martin - For: Harold Woolley and E.G. Whipple, Yoncalla Lumber Co. - April 1957 - RM 1-17 (and also see Haines Field books, H-226 & H-227)

-----  
Set 1" x 36" Angle iron with brass cap.  
BTs - 10" Fir S.75°E., 17.7 ft.  
8" Fir N.47°30'W., 19.0 ft.

Ken Hoffine - For: Juniper Properties Limited - July 2010 - M161-9

-----  
Found - 1957 BLM brass cap 0.8 ft above ground.  
Haines T-iron bears N.79°21'W., 4.45 ft  
10" D.Fir bears N.58 3/4°W., 8.0 ft (no record) healed face and BLM tag that reads S.61°E., 7.9 ft  
15" D.Fir bears S.85 1/4°E., 6.7 ft (no record) healed face and blm tag that reads N.83°W., 6.6 ft  
Corner lies on west facing slope.

Fd. BLM BC, Haines T-iron, 2 BTs - 1/2013 - K Hoffine M164-72