

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2437-38)

Set Hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S on N. face, from which
A Fir 18" dia., bears N.13°E., 22 lks. dist., mkd. ¼ S BT
A Fir 36" dia., bears S.36°W., 34 lks. dist. mkd. ¼ S BT.

J.W. Cole, County Surveyor - Wit: F.C. Sefton; W. MacFarlane
C.S. File 1/21 - Jan. 25, 1923

Renewed this corner from the original BT called for in Govt. field notes as N.13°E., 22 lks. The other tree was missing but there was a hole in proper position where the tree had burned out. I erected a mound of rocks for corner and marked new trees as follows:
A Red Fir 40" dia., S.79°W., 22.5 ft.
A Red Fir 40" dia., S.37½°E., 42.5 ft.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12700)

The ¼ sec. cor. of secs. 4 and 9, determined at record bearing and distance from the original NE. bearing trees:
A Fir 24" dia., bears N.13°E., 22 lks. dist., mkd. ¼ S9 CS
A Fir 54" dia., bears S.75°W., 36 lks. dist. mkd. ¼ S9 CS.
At the corner point
Set an iron post, 3 ft. long, 1" dia., 30" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:
$$\frac{1}{4} \begin{array}{c} S \ 4 \\ S \ 9 \end{array}$$

1955
from which
A Fir 38" dia., bears N.4½°E., 34 lks. dist., mkd. ¼ S4 BT

BLM resurvey by Joel R Herzberg, Cadastral Surveyor under Group No. 2778 - surveyed May 2015/July 2016 - (DCSO records Vol. 59 Page(s) 23557-8)

The ¼ sec. cor. of secs. 4 & 9, monumented with an iron post, 1" dia., firmly set, projecting 7" above the ground, with brass cap (properly) mkd.
from which a BT mkd. by the Douglas County Surveyor's Office, in 1923
A fir, 54" dia., bears S.37°E., 44.9 ft., with a healed blaze.
continued next page

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and a BT mkd. by the Douglas County Surveyor's Office, in 1923 and erroneously reported by Gould, et. al., in 1943-57, as an original BT

A fir, 59" dia., bears S.75°W., 21.8 ft., with a healed blaze. (Record, 23.8 ft.)

and the remains of a BT mkd. by Gould, et. al.

A fir snag, 44" dia., bears N.4½°E., 22.4 ft., with a healed blaze.

and a new bearing tree

A fir, 12" dia., bears N.29¼°W., 37.7 ft., mkd. ¼ S4 BT. Corner is located on a steep SW. facing slope.