

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 4 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1428)</p> <p>-----</p> <p>Set standard ¼ sec. post, from which A Cedar 15" dia., bears S.70°E., 41 lks. dist. A Yew 20" dia., bears S.15°W., 23 lks. dist.</p>
<p>GLO survey by Carl S. Nicklin, Deputy Surveyor, under Special Instructions dated Oct. 27, 1897 (DCSO records Vol 4 Pg 1473)</p> <p>-----</p> <p>I make diligent search, but cannot find old standard ¼ sec. cor. Set sandstone 16x12x6 ins., 10" in the ground for standard ¼ sec. cor., mkd. S C ¼ on S. face; from which A Cedar 12" dia., bears S.44°E., 19 lks. mkd. S C ¼ S BT. A Fir 20" dia., bears S.50°W., 39 lks. mkd. S C ¼ S BT. This cor. is on the SE. slope of ridge, 75 ft. above last spur.</p>
<p>BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12629)</p> <p>-----</p> <p>The standard ¼ sec. cor. of sec. 4, monumented with a sandstone, 16x12x6 ins., firmly set, mkd. SC ¼ on S. face, from which the remains of the original bearing trees: A Cedar stump, burned, 12" dia., bears S.44°E., 19 lks. A Fir 48" dia., bears S.50°W., 39 lks. dist., with a healed blaze. At the corner point Set an iron post, 3 ft. long, 1" dia., 24" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:</p> <p style="text-align: center;">----- ¼ S 4 S C 1955</p>
<p>Fd. OK - Ken Hoffine - Dec. 1995 - C.S. 65/2-1</p>
<p>BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2653, Surveyed June/July 2012 - DCSO records Vol. 58 Page(s) 22982</p> <p>-----</p> <p>The standard ¼ sec. cor. of sec. 4 only, on the N. bdy. of T. 23 S., R. 6 W., monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground, in a collar of stone, with brass cap (properly) mkd. continued next page</p>

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 4 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of a bearing tree mkd. by Nicklin
A sawed fir stump, 61" dia., bears S.50°W., 25.7 ft., with
a healed blaze.

and new accessories

An iron rod, 30" long, 5/8" dia., driven 28" in the ground
for a reference monument, bears S.30°58'11"E., 14.29
ft., with aluminum cap mkd. RM T23S R6W S4 14.3 FT TO
COR 2012 and an arrow pointing to the cor.

An iron rod, 30" long, 5/8" dia., driven 23" in the ground
for a reference monument, bears S.56°20'30"W., 18.65
ft., with aluminum cap mkd. RM T23S R6W S4 18.6 FT TO
COR 2012 and an arrow pointing to the cor.

Corner is located on a steep E. slope, 130 ft. W. of a
ravine, drains N.10°W., and 60 ft. N. of a ravine, drains
N.64°E.