

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2422)

-----  
Set Hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which  
A Fir 36" dia., bears N.40°E., 47 lks. dist. mkd. ¼ S BT.  
A Fir 4" dia., bears N.27°W., 37 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12683)

-----  
The ¼ sec. cor., determined at record bearing and distance from the only remaining bearing tree:

A Fir 36" dia., bears N.40°E., 46 lks. dist. mkd. ¼ S BT.  
At the corner point  
Set an iron post, 3 ft. long, 2" dia., 24" in the ground, with brass cap mkd:

T23SR6W  
¼  
S21 | S22  
1957

from which

A Hemlock 8" dia., bears S.11°E., 29 lks. dist. mkd. ¼ S22 BT.  
A Hemlock 9" dia., bears N.36°W., 14 lks. dist. mkd. ¼ S21 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19488)

-----  
The ¼ sec. cor. monumented with an iron post, 2½ ins. diam., firmly set, projecting 10 ins. above ground, in a collar of stone, with brass cap mkd.

T23S R6W  
¼  
S21 | S22  
1957

from which the remains of an original bearing tree

A sawed, burned fir stump, 48 ins. diam., bears N. 40° E., 49 lks. dist., no marks. (Record and to face, 46 lks.) and the remains of bearing trees mkd. by Gould, Gawron, and Eggen

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A hemlock stump, 10 ins. diam., bears S. 11° E., 29 lks. dist., with fragmentary scribe marks visible on partially healed blaze.  
A hemlock stump, 12 ins. diam., bears N. 36° W., 14 lks. dist., with healed blaze.  
and new bearing trees  
A hemlock, 20 ins. diam., bears N. 14½° E., 116 lks. dist., mkd. ¼ S22 BT.  
A cedar, 14 ins. diam., bears N. 26½° W., 67 lks. dist., mkd. ¼ S21 BT.  
The corner is located at N. edge of ravine, drains E.

Dan Saily- For: Juniper Properties, LLC - 2/2022 - M180-53  
-----  
Found - 2½" BLM brass cap (properly) marked  
49" D.Fir 3ft tall stump bears N.38¼°E., 32.5 ft with BLM tag but no visible face {record 48" N.40°E., 49 lks (32.34 ft)}  
29" Hemlock with a healed face bears N.14½°E., 76.3 ft {record 20" N.14½°E., 116 lks (76.56 ft)}  
23" Western R.Cedar with a well healed face bears N.26½°W., 44.6 ft {record 14" N.26½°W., 67 lks {44.22}}  
Top of corner monument is 0.6 ft above ground level the cap is leaning slightly southeast 0.2 ft out of plumb. Monument is on a steep east facing slope, approx. 150 ft west of a creek bottom in a second growth mixed stand and near the edge of an old growth timber stand to the northwest.