

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 472700

PRIMARY CORNER DESCRIPTION CC for Secs. 34 & 35 only, T22-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1430)

-----  
Set post C.C. to secs. 34 and 35, from which  
A Fir 14" dia., bears N.22°E., 23 lks. dist.  
A Fir 16" dia., bears N.58°W., 38 lks. dist.

GLO surveyor, Carl Nicklin, found Post in 1897 survey. DCSO records, Vol. 4 Page 1471 and Page 1476

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12626-27)

-----  
The closing cor. of secs. 34 and 35, T22S R6W, determined at record bearing and distance from the original bearing trees:  
A Fir 24" dia., bears N.26°E., 23 lks. dist., mkd. CC T22S R6W S35 BT.

A rotted Fir stump 30" dia., bears N.62°W., 38 lks. dist., no marks remaining.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

C C  
T22SR6W  
S34 S35  
T23SR6W  
S 3  
1943

from which

A Fir 24" dia., bears N.12¼°E., 26 lks. dist., mkd. T22S R6W S35 CC BT.

A Fir 18" dia., bears N.56°W., 149 lks. dist., mkd. T22S R6W S34 CC BT.

Fd. B.C., June 1992, J.Branch, M 115-26 and M 115-23