TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias Description
Alias Description
Alias Description
Alias Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2417-18)

Set Hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 20" dia., bears N.10°W., 18 lks. dist. mkd. ¼ S BT.
A Fir 30" dia., bears S.18°E., 22 lks. dist. mkd. ¼ S BT.

Survey for Elmer Kruse - April 29, 1940 - C.S. File 61/5-3

Original old stake in place. Set a new Cedar post and marked:
Fir 16", S. E. 20 lks.
Old tree, SW, A Cedar 24" (old marks plain)

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12679)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, with brass cap mkd:

¼
S3 | S2
1943

from which
A Cedar 50" dia., bears N.39°E., 21 lks. dist. mkd. ¼ S2 BT.
A Cedar 50" dia., bears S.54°W., 18 lks. dist. mkd. ¼ S3 BT.

Fd. & used on BLM corrective and dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1803 surveyed May/Nov.. 1996 - (DCSO records Vol. 52 Page(s) 19969)