

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2416-17)</p> <p>-----</p> <p>Set Cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which</p> <p style="padding-left: 40px;">A Fir 6" dia., bears N.21°W., 18 lks. dist. mkd. ¼ S BT</p> <p style="padding-left: 40px;">A Fir 7" dia., bears S.82°E., 50 lks. dist. mkd. ¼ S BT.</p>
<p>BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12678)</p> <p>-----</p> <p>Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 3 ft. long, 1" dia., 27" in the ground, with brass cap mkd:</p> <p style="padding-left: 100px;">¼ <math>\frac{S \ 2}{S \ 11}</math></p> <p>from which 1943</p> <p style="padding-left: 40px;">A Fir 16" dia., bears N.42°W., 19 lks. dist. mkd. ¼ S2 BT</p> <p style="padding-left: 40px;">A Fir 10" dia., bears S.12½°E., 15 lks. dist. mkd. ¼ S11BT</p>
<p>BLM corrective and dependent resurvey by Wayne L. Rogers, Cadastral Surveyor &amp; Robert H. Browning, Surveying Technician, under Group #1803 surveyed May/Nov.. 1996 - (DCSO records Vol. 52 Page(s) 19967-8)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 2 &amp; 11, monumented with an iron post, 1" diam., loosely set, projecting 12" above ground, with brass cap mkd.</p> <p style="padding-left: 100px;">¼ <math>\frac{S \ 2}{S \ 11}</math></p> <p style="padding-left: 100px;">1943</p> <p>from which the remains of a BT mkd. by Gould, Gawron, &amp; Eggen</p> <p style="padding-left: 40px;">A sawed fir stump, 22" diam., bears N.42°W., 19 lks., with scribe marks ¼ S2 B visible on opened blaze.</p> <p>and new bearing trees</p> <p style="padding-left: 40px;">A hemlock, 7" diam., bears S.59½°W., 57 lks. mkd. ¼ S11 BT</p> <p style="padding-left: 40px;">A fir, 5" diam., bears N.35°W., 52½ lks., mkd. ¼ S2 BT.</p> <p style="padding-left: 40px;">Reset iron post 32 " in the ground.</p>
<p>Les Roberts - For: Willamette Industries Inc &amp; McArthur &amp; Assoc. Inc. - Aug. 1997 - M127-43</p> <p>-----</p> <p>Found - 1943 GLO Iron pipe and brass cap</p> <p style="padding-left: 40px;">6" hemlock, N.37°W., 34.3' (scribe visible), no rec.</p> <p style="padding-left: 40px;">6" hemlock, S.59°W., 37.6' (scribe visible), no rec</p> <p style="text-align: right;">cont.</p>

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22845)

-----  
The ¼ sec. cor. of secs. 2 and 11, monumented with an iron post, 1" dia., firmly set, projecting 7" above a collar of stone, with a brass cap (properly) mkd. from which the remains of a bearing mkd. by Gould, Gawron, and Eggen

A decayed fir stump, 22" dia., bears N.42°W., 12.5 ft., with no marks visible.

and bearing trees mkd. by Rogers and Browning in 1996

A hemlock, 16" dia., bears S.59½°W., 37.6 ft., with a healed blaze.

A hemlock, 10" dia., bears N.36¾°W., 34.8 ft., with a healed blaze. (Record, N.35°W., 37.6 ft.)

Corner is located 6 ft. E. of a creek, 1 ft. wide, course N.10°W.