

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 572700

PRIMARY CORNER DESCRIPTION C C for Secs. 35 & 36 only, T22-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1430)

Set C. C. to secs. 35 and 36, from which
A Laurel 18" dia., bears N.78°W., 28 lks. dist.
A Fir 12" dia., bears N.46°E., 60 lks. dist.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12625)

Point for the closing cor. of secs. 35 and 36, T22S R6W, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

C C
T22SR6W
S35|S36
T23SR6W
S 2
1943

from which
A Fir 36" dia., bears N.80°E., 37 lks. dist., mkd. T22S R6W S36 CC BT.
No tree is available in the NW. quadrant.
A Fir 32" dia., bears S.60°W., 87 lks. dist., mkd. XBT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Wm. Stoffel & M Stone, crew - Feb. 26, 1964 - C.S. File 49/143-96

Found - GLO brass cap set in 1943.
36" Fir snag, dead and rotting, N.80°E., 24.4 ft., scribing visible "T22S R6W S36 CC"
32" W.Fir N.60°W., (not S.60°W.), very plain scar visible.
New BT - 11" W.Fir N.33°E., 97.3 ft. mkd. "T22S R6W CC S36 CS BT.

Fd. OK, June 1992, J.Branch, M 115-26
Fd. OK, Aug. 1992, R.Brandt, M 115-52
Fd. OK, Aug. 1994, K.Hoffine, M 120-79

continued next page

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 572700

PRIMARY CORNER DESCRIPTION C C for Secs. 35 & 36 only, T22-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM corrective and dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1803 surveyed May/Nov.. 1996 - (DCSO records Vol. 52 Page(s) 19957-8)

The cor. of secs. 35 & 36 only, T. 22 S., R. 6 W., monumented with an iron post, 1¼" diam., badly bent, projecting 12" above ground, with brass cap mkd. CC T22S R6W S35 S36 T23S R6W S2 1943, from which the remains of a bearing tree mkd. by Gould, Gawron, and Eggen:

A roothole, bears N.60°W., 87 lks., with uprooted fir alongside, 39" diam., with healed blaze. (Rec. S.60°W.) from which the remains of BTs mkd. Godfrey, in 1964, recorded in the Douglas County Surveyors Office, CS File No. 49/143

A fir, 25" diam., bears N.33¼°E., 146½ lks., with healed blaze.

and a new bearing tree

A fir, 17" diam., bears N.52¼°W., 57½ lks., mkd. T22S R6W S35 BT.

At the corner point, remove iron post and set a stainless steel post, 28" long, 2½" diam., 26" in the ground, with brass cap mkd.

T 22 S R 6 W
S 35 | S 36
S 2
T 23 S R 6 W
1996

This corner was set concurrently with the corners of the Fifth Standard Parallel South, making it a corner of minimum control, not a closing corner.