

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2402)

Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ on W. face, from which
A Fir 20" dia., bears N.10°E., 35 lks. dist. mkd. ¼ S BT.
A Fir 20" dia., bears S.40°W., 28 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12664)

The ¼ sec. cor., determined at record bearing and distance from an original bearing tree:

A rotted Fir stump 24" dia., bears S.40°W., 28 lks. dist. mkd. 4 S BT.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

¼
S14|S13
1957

from which

A Fir 6" dia., bears S.47°E., 10 lks. dist. mkd. ¼ S13 BT
A Fir 8" dia., bears West, 62 lks. dist. mkd. ¼ S14 BT.

BLM corrective and dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1803 surveyed May/Nov.. 1996 - (DCSO records Vol. 52 Page(s) 19962)

The ¼ sec. cor. of secs. 13 & 14, monumented with an iron post, 1" diam., firmly set, projecting 12" above ground, with brass cap mkd.

T 23 S R 6 W
¼
S 14 | S 13
1957

from which the remains of BTs mkd. by Gould, Gawron, & Eggen

A fir, 14" diam., bears S.47°E., 10 lks., with healed blaze.

A roothole, bears West, 62 lks., with uprooted fir alongside, 9" diam., with healed blaze.

and a new bearing tree

A fir, 8" diam., bears S.11°W., 27 lks., mkd. ¼ S14 BT.

continued next page

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22857)

The ¼ sec. cor. of secs. 13 & 14, monumented with an iron post, 1" dia., firmly set, projecting 15" above ground, with a brass cap (properly) mkd.

from which the remains of BTs mkd. by Gould, Gawron, & Eggen
A fir, 18" dia., bears S.47°E., 6.6 ft., with a healed blaze.

A roothole bears West, 40.9 ft., downhill of which is a down, decayed fir snag, 9" dia., with no marks visible. and a bearing tree mkd. Rogers and Browning in 1996

A fir, 11" dia., bears S.11°W., 17.8 ft., with a healed blaze.

Corner is located 200 ft. E. of a spur, slopes N.35°E.