

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2405)

Set a Dogwood post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor., mkd. 1/4 S on W. face, from which
 A Fir 18" dia., bears S.10°E., 13 lks. dist. mkd. 1/4 S BT.
 A Maple 4" dia., bears N.40°W., 25 lks. dist. mkd. 1/4 S BT

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12666)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
 Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

$$\begin{array}{c} \frac{1}{4} \\ S11 | S12 \\ 1943 \end{array}$$

from which
 A Fir 31" dia., bears N.7°E., 97 lks. dist. mkd. 1/4 S12 BT.
 A Fir 25" dia., bears N.39°W., 97 lks. dist. mkd. 1/4 S11 BT

Fd. OK, June 1981, B. Shaner, M 79-78
Fd. OK, March 1990, K.Hoffine, C.S. File 63/104-51

BLM corrective and dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1803 surveyed May/Nov.. 1996 - (DCSO records Vol. 52 Page(s) 19964-5)

The 1/4 sec. cor. of secs. 11 & 12, monumented with an iron post, 1 1/4" diam., firmly set, projecting 9" above ground, with brass cap mkd.

$$\begin{array}{c} \frac{1}{4} \\ S 11 | S 12 \\ 57 \\ 1943 \end{array}$$

from which the remains of BTs mkd. by Gould, Gawron, & Eggen
 A fir, 45" diam., bears N.7°E., 97 lks. with healed blaze.
 A sawed fir stump, 33" diam., bears N.39°W., 97 lks., with healed blaze, covered with a tin cap.
 and a new bearing tree
 A fir, 11" diam., bears N.70°W., 15 lks., mkd. 1/4 S11 BT.

FD BC by D. Edwards, 4/2012 - M163-72