

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2402)

 Set Dogwood post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which
 A Fir 8" dia., bears S.18°W., 21 lks. dist. mkd. ¼ S BT.
 A Fir 16" dia., bears N.20°W., 39 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12663-64)

 Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post 3 ft. long, 1" dia., 27" in the ground with brass cap mkd:
 ¼ S 13
 S 24
 1943

from which
 A Fir 45" dia., bears N.45°E., 82 lks. dist., mkd. ¼ S13 BT.
 A Fir 16" dia., bears S.60°W., 65 lks. dist., mkd. ¼ S24 BT.

Wilford N. Haines, - For: Yoncalla Lumber Co. - Aug. 1961 - M 23-33

 Found - GLO brass cap set in 1943
 45" Fir N.45°E., 82 lks., down.
 18" Fir S.70°W., 65 lks., down.
 Scribed new trees:
 10" Fir S.66°E., 6.5 ft.
 14" I.Cedar N.65°W., 122.8 ft. This tree on top of ridge on West side of cat road.

BLM corrective & dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1803 surveyed May/Nov.. 1996 - (DCSO records Vol. 52 Page(s) 19953-4)

 The ¼ sec. cor. of secs. 13 & 24, monumented with an iron post, 1" diam., firmly set, projecting 8" above ground, with brass cap mkd.

 S 13
 ¼ S 24
 1943

continued next page

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of bearing trees mkd. by Gould, Gawron, and Eggen

A roothole, bears N.45°E., 82 lks., with uprooted trunk alongside, size undeterminable, no marks visible.

A roothole, bears S.60°W., 65 lks., with uprooted trunk alongside, 16" diam., no marks visible.

and the remains of a bearing tree mkd. by Haines, in 1961, recorded in the Douglas County Surveyors Office Map File No. M23-33

A sawed fir stump, 15" diam., bears S.66½°E., 9 lks., with healed double blaze.

and new bearing trees

A fir, 17" diam., bears N.17¼°E., 39 lks., mkd. ¼ S13 BT.

A fir, 13" diam., bears S.60¼°W., 25 lks., mkd. ¼ S24 BT.