

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & S. 6, T23-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2339)

Set ¼ sec. post, from which
A Fir 30" dia., bears S.48°E., 57 lks.
A Fir 24" dia., bears S.35°W., 48 lks.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12641)

The ¼ sec.cor., perpetuated with a stake 30" long, 4" sq., firmly set, mkd. ¼ on W. side, from which the original bearing trees:

A Fir stump 36" dia., bears S.48°E., 57 lks. dist., marks burned off.
A Fir stump 30" dia., bears S.35°W., 48 lks. dist., mkd. BT.

At the corner point
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, with brass cap mkd: ¼
S 1 | S 6
1943

from which
A Fir 6" dia., bears N.84°E., 30 lks. dist. mkd. ¼ S6 BT
A Fir 26" dia., bears S.76½°W., 70 lks. dist. mkd. ¼ S1 BT

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - R.B. Kimberling, crew - April 12, 1977 - C.S. File 59/31-23

Found - 1943 GLO brass cap on 1" pipe (OD) 13" above ground properly mkd.
A Fir stump, decayed, orig. 36" now indeterminate, bears S.48°E., 37.6 ft. No visible scribing.
A Fir stump, badly decayed, 24" bears S.35°W., 32.9 ft. with open blaze mkd. ¼ S (Rec. 31.7 ft.)
A Fir snag 20 ft. high, 24" dia., bears N.84°E., 19.1 ft. with well healed blaze. (Rec. 19.8 ft.)
A Fir stump 29", bears S.76½°W., 46.2 ft. One open blaze, scribing chopped out.
New BTs -18" B.Oak bears S.69°W., 33.3 ft. blazed and mkd. ¼ S1 CS BT.
8" D.Fir bears S.60½°E., 21.1 ft., double blazed and mkd. ¼ S6 CS BT.
Corner lies approx. 36 ft. North of old road.

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & Sec. 6, T23-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. and Used in BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/August 22, 1995 - (DCSO records Vol. 51 Page(s) 19462-63)