

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T23-8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2458)

- 
- Set post cor. to secs. 7 and 18, 12 & 13, from which
- A Laurel 16" dia., bears N.5°E., 31 lks. dist.
  - A Fir 5" dia., bears S.60°E., 30 lks. dist.
  - A Laurel 5" dia., bears S.16°W., 37 lks. dist.
  - A Fir 5" dia., bears N.20°W., 17 lks. dist.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group # 518 - surveyed June/July 1963 - (DCSO records Vol. 32 Page(s) 13534-35)

- 
- The Sec. cor., determined at record bearing and distance from the remaining original bearing trees;
- A stump hole bears N.5°E., 31 lks. dist.
  - A sawed Fir stump 38" dia., bears S.60°E., 30 lks. dist., with faint axe marks visible on opened blaze.
  - A rotted Fir stup size indeterminate, bears N.20°W., 17 lks. dist., with no marks visible.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:

T 23 S
R 8 W R 7 W
<u>S 12 S 7</u>
S 13 S 18
1964

- from which new bearing trees
- A Fir 3" dia., bears N.23°E., 47 lks. dist. mkd. T23S R7W S7 BT.
  - A Fir 8" dia., bears S.82½°E., 86 lks. dist. mkd. T23S R7W S18 BT.
  - A Fir 15" dia., bears S.28°W., 286 lks. dist. mkd. T23S R8W S13 BT.
  - A White Fir 6" dia., bears N.73½°W., 79 lks. dist. mkd. T23S R8W S12 BT.

BLM resurvey by John A. Farmer, Cadastral Surveyor, under Group #1336, Surveyed Aug/Oct. 1986 - (DCSO records Vol. 48 Page(s) 18280-81)

- 
- The Sec. cor. determined at record bearing and distance from the remains of an original bearing tree:
- A rotted Fir stump, size indeterminate, bears S.60°E., 30 lks. dist., with axe marks and chaining notch visible on open blaze.

(Cont. Next Page)

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T23-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, the cor. of secs. 7, 12, 13 and 18, erroneously accepted as original by Brooks and Peterson, bears N.80°37'E., 1.161 chs. dist., monumented with an iron post 3½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witness as described in the official record.

I remove the iron post, destroy the marks on the bearing trees, and at the true corner point:

Reset the iron post, 28" long, 2½" dia., 24" in the ground with brass cap mkd.

T 23 S  
R 8 W      R 7 W  
S 12 S 7  
S 13 S 18  
1986

from which new bearing trees:

- A Fir 10" dia., bears N.19 3/4°E., 33 lks. dist.mkd. T23S R7W S7 BT.
- A Fir 15" dia., beas S.80½°E., 34 lks. dist. mkd. T23S R7W S18 BT.
- A Fir 14" dia., bears S.51 3/4°W., 56 lks. dist. mkd. T23S R8W S13 BT.
- A Fir 13" dia., bears N.71¼°W., 55 lks. dist. mkd. T23S R8W S12 BT.